

Inop: Incubator O/R: Reagent Sup



DIAGNOSTICS - Calibrate Luminometer

DAC Values

Review the DAC values from before and after the calibration.

Setting	Before	After
High Voltage Setting:	3569	3569
Discriminator DAC Setting:	1699	1699
Analog Offset DAC Setting:	2026	2026
Luminometer Reference Intensity DAC Setting:	2606	2606
Incubator Reference Intensity DAC Setting:	2864	2846

OK

Help

... was successful.



IRS
Calibration



Full
Calibration

