

Metropolis Healthcare Ltd., EQAS

Analyte Methodwise Result Report

Lab: 836
Lab Name: SHREE VIGHNAHARTA SUPERSPECIALITY HOSPITAL

Report Date : 13/02/2024 Sample Date : 23/12/2023


Haematology - CBC, Platelet Count, 1000/ µL


Comparative Statistics	N	Mean	SD	CV%	Excluded
All Methods	222	218.96	22.67	10.35	24
Impedance - (Your Method)	212	220.01	22.47	10.21	21
ERBA H 360 - (Your Analyzer)	5	235.75	26.95	11.43	1

Evaluation Based On - Equipment wis	e Peer Grouping		
Your Result	223.00	SDI / z-Score	-0.03
Assigned Value	223.75	Average SDI	0.53
SDPA	22.305	Uncertainity of AV	5.58
Standard Unit Result Val	223.00	%DEV	-5.41

Note: # - Not evaluated / Bimodal distribution


X: SDI more than 4






Cycle No: 230412

Sample No: 04








Lab: 836

Metropolis Healthcare Ltd., EQAS

Analyte Methodwise Result Report

Lab Name: SHREE VIGHNAHARTA SUPERSPECIALITY HOSPITAL

Sample No: 04 Report Date: 13/02/2024 Sample Date: 23/12/2023



Cycle No: 230412

Note SDI with * marked are not considered for evaluation

Comments:

Haematology - CBC, Platelet Count									
		N	Mean	SD	CV%	Excluded			
	All Analyzer	222	218.96	22.67	10.35	24			
Your Analyzer :	ERBA H 360	5	235.75	26.95	11.43	1			
	Horiba Yumizen H550	44	227.36	18.07	7.95	4			
	Sysmex XP-100	25	208.48	17.77	8.53	2			
	Horiba Yumizen H500	22	216.30	20.15	9.31	2			
	Nihon Kohden Celltac Alpha	21	236.35	21.55	9.12	-			
	Mindray BC-5000	14	216.77	9.71	4.48	1			
	Erba ELite 580	13	218.33	10.94	5.01	1			
	Horiba ABX Micros ES 60	10	221.70	23.84	10.75	-			

Remarks: Interpretation of your reports

a) If your SDI lies between +/- 2.0 SDI then your results are well within limits.

b) If your SDI lies between +/-2.0 to 2.99 SDI then it is a warning alert flag.

c) If your SDI is +/- 3.0 SDI or more then it is an action alert flag.

Interpretation when an analyte is reported for multiple samples in a Round:

a) Reported on 2 samples:

• Two out of two pass

- Acceptable performance

• One out of two pass

- Review for random error & take action if appropriate

· Both failed

- Unacceptable performance, Review for systematic error

b) Reported on 3 samples:

· All pass

- Acceptable performance

• Two out of three pass

- Review for random error & take action if appropriate

· One out of three pass

- Unacceptable performance, Review for systematic error

All failed

- Unacceptable performance, Review for systematic error



Dr Puneet Kumar Nigam

PT coordinator & Technical Manager, MHL EQAS

Unit No. 409-416. Commercial Building - 1A Kohinoor Mall, Kirol Road, Kurla (W),

Mumbai - 400070



