



Metropolis Healthcare Ltd., EQAS

KRSNAA DIAGNOSTICS LTD KULLU (1242)

Outlier And Analyte Summary Report

Outlier Details For Cycle No 240104 and Sample No 02

Report Date : 10/07/2024

Analyte	Instrument	Result Value	Standard Unit	Z-Score
No Outlier				
Legend @ : z score \leq 2.0 - Acceptable ! : 2.0 < z score < 3.0 - Warning X : z score \geq 3 - Unacceptable # : Not Evaluated ⌚ : Delayed Result Entry * : Not considered for evaluation.				

Problem Classification: _____

Corrective Action: _____

Reviewed by: _____

Dated: _____

Instrument : Diasys 200 Pro


Analyte	Standard Unit	Result Value	Mean	Z-Score	RMZ
@ Glucose	mg/dl	77.70	71.18	0.02	0.02
@ Urea	mg/dl	25.60	26.57	0.02	0.06
@ Creatinine	mg/dl	0.90	0.99	-0.60	-0.69
@ Bilirubin Total	mg/dl	0.50	0.35	1.37	1.35
@ Bilirubin Direct	mg/dl	0.10	0.14	0.10	-0.10
@ Total Protein	g/dL	7.85	7.58	0.69	0.62
@ Albumin	g/dL	4.50	4.19	1.12	1.30
@ Uric Acid	mg/dl	4.41	4.32	-0.23	-0.36
@ Calcium	mg/dl	9.41	8.55	0.70	1.03
@ Cholesterol	mg/dl	171.00	162.79	0.12	-0.08
@ Triglycerides	mg/dl	129.00	135.91	-0.58	-0.32
@ HDL	mg/dl	33.00	29.24	0.19	0.37
@ ALT	U/L	7.60	5.92	1.14	1.15
@ AST	U/L	15.27	13.94	0.19	0.63
@ ALP	U/L	53.94	45.36	-0.10	-0.33

Instrument : Yumizen E100

Analyte	Standard Unit	Result Value	Mean	Z-Score	RMZ
@ Chloride	mmol/L	103.05	--	0.68	0.86
@ Sodium	mmol/L	122.60	--	-1.25	0.25
@ Potassium	mmol/L	5.75	--	1.30	2.49

Legend @ : Acceptable
 ! : 2.0 < z score < 3.0 - Warning
 X : z score ≥3 - Unacceptable
 # : Not Evaluated
 ⊙ : Delayed Result Entry
 * : Not considered for evaluation.

Total Parameters	18
Not Evaluated Parameters	0
Evaluated Parameters	18
Outlier Parameters (X)	0
EQAS Score Biochemistry	100.00 %



Dr Puneet Kumar Nigam
 PT coordinator & Technical Manager, MHL EQAS
 Unit No. 409-416.
 Commercial Building - 1A
 Kohinoor Mall, Kirol Road, Kurla (W),
 Mumbai - 400070



Metropolis Healthcare Ltd., EQAS

KRSNAA DIAGNOSTICS LTD KULLU (1242)

Outlier And Analyte Summary Report

Outlier Details For Cycle No 240104 and Sample No 02

Report Date : 10/07/2024

Analyte	Instrument	Result Value	Standard Unit	Z-Score
No Outlier				
Legend @ : z score \leq 2.0 - Acceptable ! : 2.0 < z score < 3.0 - Warning X : z score \geq 3 - Unacceptable # : Not Evaluated ⌚ : Delayed Result Entry * : Not considered for evaluation.				

Problem Classification: _____

Corrective Action: _____


Reviewed by: _____

Dated: _____

Instrument : Lifotronic H-9

Analyte	Standard Unit	Result Value	Mean	Z-Score	RMZ
@ HbA1c	%	7.60	7.75	0.37	0.65

Legend @ : Acceptable	Total Parameters	1
! : 2.0 < z score < 3.0 - Warning	Not Evaluated Parameters	0
X : z score ≥3 - Unacceptable	Evaluated Parameters	1
# : Not Evaluated	Outlier Parameters (X)	0
⌚ : Delayed Result Entry	EQAS Score HbA1c	100.00 %
* : Not considered for evaluation.		



Dr Puneet Kumar Nigam
PT coordinator & Technical Manager, MHL EQAS
Unit No. 409-416.
Commercial Building - 1A
Kohinoor Mall, Kiroil Road, Kurla (W),
Mumbai - 400070



Metropolis Healthcare Ltd., EQAS

KRSNAA DIAGNOSTICS LTD KULLU (1242)

Outlier And Analyte Summary Report

Outlier Details For Cycle No 240104 and Sample No 01

Report Date : 10/07/2024

Analyte	Instrument	Result Value	Standard Unit	Z-Score
No Outlier				
Legend @ : z score \leq 2.0 - Acceptable ! : 2.0 < z score < 3.0 - Warning X : z score \geq 3 - Unacceptable # : Not Evaluated ⌚ : Delayed Result Entry * : Not considered for evaluation.				

Problem Classification: _____

Corrective Action: _____


Reviewed by: _____

Dated: _____

Instrument : Lifotronic H-9

Analyte	Standard Unit	Result Value	Mean	Z-Score	RMZ
@ HbA1c	%	5.30	5.35	0.93	0.65

Legend @ : Acceptable	Total Parameters	1
! : 2.0 < z score < 3.0 - Warning	Not Evaluated Parameters	0
X : z score ≥3 - Unacceptable	Evaluated Parameters	1
# : Not Evaluated	Outlier Parameters (X)	0
⌚ : Delayed Result Entry	EQAS Score HbA1c	100.00 %
* : Not considered for evaluation.		



Dr Puneet Kumar Nigam
PT coordinator & Technical Manager, MHL EQAS
Unit No. 409-416.
Commercial Building - 1A
Kohinoor Mall, Kiroil Road, Kurla (W),
Mumbai - 400070