



**BECKMAN
COULTER.**

Beckman Coulter India Pvt. Ltd.

FIELD SERVICE REPORT

No.: **5834**

Date: **22/11/2019**

CUSTOMER NAME: Dr. Anesh Mehta			MODEL: DXI 800		
Apple Diagnostic			SERIAL NO: 601255		
WARRANTY:	ACTIVE OWNED	OTL	INSTANCE NO: 28214741		
			SERVICE REQUEST NO. (S.R NO.): 31720343		
			TASK NO: 103520642		
DEPARTMENT:			DATE	TIME	TYPE OF CALL
CONTACT PERSON: Dr. Anesh Mehta		COMPLAINT RECD			INSTALLATION
ADDRESS: Ghatkopar		RESPONSE	22/11/19	10:30 AM	DE-INSTALLATION
		COMPLETION	22/11/19	6:00 PM	PM VISIT <input checked="" type="checkbox"/>
			HRS	MINS	BREAKDOWN
CITY / POSTAL CODE: Mumbai		LABOUR HRS			MODIFICATION
STATE / COUNTRY: Maharashtra / India		TRAVEL HRS			APPLICATION
MOB.TEL. No.:		TOTAL HRS			
E-MAIL:					

PROBLEM REPORTED/ SYMPTOM: **Preventive Maintenance**

OBSERVATIONS/ CAUSE: **—**

ACTION TAKEN/ RESOLUTION: **Carried out Preventive Maintenance of the instrument as per the procedure.**

VERIFICATION OF REPAIR: **QE System check passed. QC results found satisfactory.**

VERIFICATION STATEMENT

FOLLOWING PARTS HAVE BEEN REPLACED FROM - BECKMAN COULTER <input checked="" type="checkbox"/> OR CUSTOMER STOCK <input type="checkbox"/>						
Sr. No.	PART No.	DESCRIPTION	UNIT PRICE	QTY	TOTAL	NS
1	B21386	Kit, DXI 800 PM		1		
2						
3						
4						
(Taxes Extra) TOTAL Rs.						

ADDITIONAL COMMENTS:

CF RAISED Y / N IF YES CF TYPE -

We approve the above charges.
I certify that the above work has been carried out to my satisfaction.

 ENGINEERS NAME & SIGNATURE	CHECKED BY	 CUSTOMER SIGNATURE
--------------------------------	------------	------------------------