



**Beckman Coulter India Pvt. Ltd.
3rd floor, B-wing,
Art Guild House
Phoenix Market City
LBS Road, Kurla (W)
Mumbai- 400 070
Ph: 022 30805000**

Date: 5th March 2020

Calibration Certificate

Analyzer Model: Access2
Instrument Serial no. : 507429
Installed at: Arpan Diagnostic Centre
Calibrated on: 05/3/2020
Next calibration due: 06/3/2021

We hereby confirm that Beckman Coulter Access2 has been successfully calibrated and passed All quality check and is working in good condition.

For, Beckman Coulter India Pvt. Ltd.

A handwritten signature in black ink that reads 'Amit'.

Amit Vishvakarma
Customer Support Engineer



Beckman Coulter India Pvt. Ltd.
3rd floor, B-wing,
Art Guild House
Phoenix Market City
LBS Road, Kurla (W)
Mumbai- 400 070
Ph: 022 30805000

Calibration Certificate

05th March, 2020

This is to certify that Access 2 (SR. NO. 507429) installed at Arpan Diagnostic Centre Rajkot, as calibrated as per the recommended procedures.

The system parameters as mentioned below were verified and necessary calibrations done as applicable.

System temperatures

Temperature Sensor	Temperature (°C)	Operating range (°C)
Refrigerator	3.50	1.00 to 05.00
Incubator Wheel	36.38	36.13 to 36.73
Substrate	36.48	36.23 to 36.63
Wash Wheel	36.42	36.23 to 36.63
Instrument Case	27.07	18 to 36

Power Supply Units

Power Supply	Measured (V)	Tolerances (V)
+24V	24.05	1.2V
+12V	12.01	0.4V
+5V	5.00	0.2V
-5.2V	-5.21	N.A.
-12V	-12.01	0.4V

All the parameters are within the specified Limits.

For Beckman Coulter India Pvt. Ltd.

Amit Vishvakarma
Customer Support Engineer