

Delhi Office:

84, Lal Singh Building, 2nd Floor, 205-206, Near Aggarwal Sweets,
Vasant Kunj Road, Manpalpur, New Delhi-110 037, INDIA.
Tel.: (011) 46062637 / 38 / 39 Fax : (011) 46062640.
E-mail: tulipdelhik@yahoo.co.in, tulipdelhik@gmail.com

TO WHOM SO IT MAY CONCERN

This is to certify that the Cumcell-23 Plus V2 having
serial number M10011805056 installed at Atabu Path Lab
was checked and evaluated with a third party material with known values,
on 04-10-2020 and was found to be working satisfactorily.

Next calibration due on: Nov-2020.

Calibration Report

Hardware Calibration: OK	<input checked="" type="checkbox"/>	NOT OK	<input type="checkbox"/>
Reagent Temperature: OK	<input checked="" type="checkbox"/>	NOT OK	<input type="checkbox"/>
Humidity: OK	<input checked="" type="checkbox"/>	NOT OK	<input type="checkbox"/>

Delhi Office:

84, Lal Singh Building 2nd Floor, 205-206, Near Aggarwal Sweets,
Vasant Kunj Road, Manpalpur, New Delhi-110 037, INDIA.
Tel.: (011) 46062637 / 38 / 39 Fax : (011) 46062640.
E-mail: tulipdelhi@yahoo.co.in, tulipdelhi@gmail.com

Third Party Material L1				
Parameter	Obtained Value	Range	Remark	
WBC	2.24	1.80-2.80	PASS ✓	FAIL
RBC	1.98	2.01-2.41	PASS ✓	FAIL
HGB	6.2	5.80-7.0	PASS ✓	FAIL
MCV	88.0	78.2-90.2	PASS ✓	FAIL
PLT	98	57-107	PASS ✓	FAIL
Third Party Material L2				
Parameter	Obtained Value	Range	Remark	
WBC	6.68	5.57-7.57	PASS ✓	FAIL
RBC	4.40	4.26-4.86	PASS ✓	FAIL
HGB	13.0	12.9-14.3	PASS ✓	FAIL
MCV	94.0	84.7-96.7	PASS ✓	FAIL
PLT	240	171-261	PASS ✓	FAIL

Third Party Material L3				
Parameter	Obtained Value	Range	Remark	
WBC	17.05	13.86-18.86	PASS	FAIL
RBC	5.88	5.26-6.01	PASS	FAIL
HGB	17.4	16.7-18.3	PASS	FAIL
MCV	101.0	91.6-103.6	PASS	FAIL
PLT	455	348-478	PASS	FAIL

Evaluation done by:

Sanjeer Tiwari

QC- OFFICER.

Tulip Diagnostics (P) Ltd.

Place: Delhi