

Ace Medical Solutions (India) Pvt. Ltd.

An ISO 9001-2015 Certified Company

No : 3/751, 1st Cross Street, Surveyor Colony, K.Pudur, Madurai - 625 007.

Phone : 0452 - 2561691 Mobile : +91 94434 74610



GSTIN. 33AAHCA8053H1ZR

DL No. MDU/4205/20B, MDU/3971/21B

CIN: U33110TN2009PTC072140

CALIBRATION CERTIFICATE

Customer	M/S. Jeyam Clinical Lab,	Certificate No:	AMS/LAB/2887256
Name &	K.Pudur, Ayyappan Kovil,	Issuing Date:	03/01/2020
Address:	Madurai.	Page No:	1 of 2

Details of Device under Calibration (DUC):

DUC:	Microscope	Id. No:	JCL/AYKL/MS/001
Make:	SH	Department:	Laboratory
Model:	Research Micro Scope	Calibrated On:	02/01/2020
SI. No:		Calibration	
Type:	Electric	Due Suggested:	01/01/2021
Range &		DUC Condition	
Least Count:		on Receipt:	OK

Traceability Details:

Sl.No.	Test Equipment	Make .	Certificate Number	Valid Up to
1	Electrical Safety Analyser	RigelSafeTest60	PSG/CIRD/BMCC/3879/2019	20/01/2020
2 .	Digital Lux Meter	HTC/LX - 103	FSMS/CL/05/19-07/NN050-01	31/07/2020
3	Thermo Hygrometer	HTC	-QC/MD/20190218	10/02/2020

Room Temperature: 25°C±2

Room Humidity: 30-60%

(At the time of Calibration)

ESA Test Results:

SL.No	Parameter	ESA Reading	Unit	Normal Range	Condition
1	Current	0.83	Amps	1	Normal
2	Frequency	50.1	Hz	49 -50	Normal
3	Mains Voltage Line - Neutral	230.8	Volts	220 - 240	Normal
4	Mains Voltage Line - Earth	233.5	Volts	220 - 240	Normal
5	Mains Voltage Neutral - Earth	5.1	Volts	< 7	Normal

^{*}Electrical Safety: Please check the attached log sheet

SL.No.	Knob Position	DUC Reading (LUX)	Distance (Cm)
1	Low	3400	5.0
2	Medium	14600	5.0
3	High	34200	5.0

Note:

- 1. Calibration Points were selected as per customer request.
- Each reading were taken by Repeatability Test
 (i.e.) each reading in a row is a mean of 10 readings.
- Results Reported are valid at the time of and under the stated conditions of measurements.

Calibrated By:

(Calibration Engineer)









