Ace Medical Solutions (India) Pvt. Ltd.

An ISO 9001-2015 Certified Company No: 3/751, 1st Cross Street, Surveyor Colony, K.Pudur, Madurai - 625 007.

Phone: 0452 - 2561691 Mobile: +91 94434 74610



GSTIN, 33AAHCA8053H1ZR

DL No. MDU/4205/20B,MDU/3971/21B
CIN: U33110TN2009PTC072140

CALIBRATION CERTIFICATE



Customer	M/s. Srinivasa X-Ray & Clinical Laboratory,	Certificate No:	AMS/LAB/2888266
Name &	83,A.K.S Theatre road,	Issuing Date:	21/09/2020
Address:	Kovilpatti - 628502.	Page No:	1 of 1

Details of Device under Calibration (DUC):

DUC:	Centrifuge	. Id. No:	SCL/LAB/CEN/003
Make:	Lab	Department:	Laboratory
Model:	8 Bkts	Calibrated On:	19/09/2020
Sl. No:		Calibration	
Type:	Manual	Due Suggested:	18/09/2021
Range &	0 – 3500 / LC - 1	DUC Condition	
Least Count:	£"	on Receipt:	OK

Traceability Details:

Sl.No.	Test Equipment	Make	Certificate Number	Valid Up to
1	Digital Tachometer	Lutron / DT-2234C	FSMS/CL/05/18-08/071-01	29/07/2021
2	Thermo Hygrometer	HTC	QC/AMS-DTI-004	22/02/2021

Room Temperature: 25°C±2

Room Humidity: 30-60%

(At the time of Calibration)

Test Results:

SL.No.	DUC Reading positions	Standard Reading (RPM)	Correction (RPM)
1	Position 1	1872	0
2	Position 2	. 2345	. 0
3	Position 3	2568	0
4	Position 4	2853	. 0
5	Position 5	3186	. 0

Allowable Tolerance: Set by Customer

Note:

- 1. Calibration Points were selected as per customer request.
- 2. Each reading were taken by Repeatability Test (i.e.) each reading in a row is a mean of 10 readings.
- 3. Results Reported are valid at the time of and under the stated conditions of measurements.

Calibrated By:

(Calibration Engineer)

@ aceagm@gmail.com

@ww.acemedical.in





Approved by:

(Technical Manager)

B. 89.

93455 56140, 93455 56148