



## CALIBRATION CERTIFICATE

Certificate No.	MES/20-21/GHPI/CEN/D01	Date of Issue : 19/12/2020
		Calibration Done On : 19/12/2020
		Calibration Due On : 18/12/2021

Customer Name	<b>GENERAL HOSPITAL, PALAI.</b>
---------------	---------------------------------

### DETAILS OF DEVICE UNDER CALIBRATION

Equipment Name	Make / Model	Serial No.	Asset ID	Location
Centrifuge	Rotek	0803	68050892	ICTC Lab

### DETAILS OF MASTER EQUIPMENT USED

Sl No.	Master Equipment	Make / Model	Serial No.	Reference ID	Cal. Due
1	Digital Tachometer	Equinox / EQ-801B	S916577	ACS/20-21/I02671-01	24/09/2021
2	Digital Thermo Hygrometer	Equinox / EQ-308-CTH	20191602	ACS/MC/20-21/2593-01	18/06/2021

The instruments used for calibration are under valid calibration and are traceable to National Standards.

<b>Environmental Conditions</b>	Temperature	27°C	Relative Humidity	55 %
---------------------------------	-------------	------	-------------------	------

### PERFORMANCE DATA

Set Reading	Display Reading	Measured Reading	Tolerance
Minimum	1500 rpm	1501 rpm	± 5 rpm
Medium	2600 rpm	2601 rpm	± 5 rpm
Maximum	3600 rpm	3602 rpm	± 5 rpm

<b>Calibration Status</b>	Pass	✓	Fail	
---------------------------	------	---	------	--

Calibrated By

Prabin KP (Service Engineer)

Approved By



Binoj Thomas (Quality Manager)



## CALIBRATION CERTIFICATE

Certificate No.	MES/20-21/GHPI/REF/D01	Date of Issue : 19/12/2020
		Calibration Done On : 19/12/2020
		Calibration Due On : 18/12/2021

Customer Name	<b>GENERAL HOSPITAL, PALAI.</b>
---------------	---------------------------------

### DETAILS OF DEVICE UNDER CALIBRATION

Equipment Name	Make / Model	Serial No.	Asset ID	Location
Refrigerator	Electrolux	-	68058064	ICTC Lab

### DETAILS OF MASTER EQUIPMENT USED

Sl No.	Master Equipment	Make / Model	Serial No.	Reference ID	Cal. Due
1	Digital Thermometer	Metravi / DTM 900	10055593	ACS/20-21/I02669-01	23/09/2021
2	Digital Thermo Hygrometer	Equinox / EQ-308CTH	20191602	ACS/MC/20-21/2593-01	18/06/2021

The instruments used for calibration are under valid calibration and are traceable to National Standards.

<b>Environmental Conditions</b>	Temperature	27 °C	Relative Humidity	55 %
---------------------------------	-------------	-------	-------------------	------

### PERFORMANCE DATA

Display	Measured	Tolerance
1.3 °C	1.2 °C	± 0.3 °C
2.4 °C	2.4 °C	± 0.3 °C
4.2 °C	4.3 °C	± 0.3 °C
7.2 °C	7.2 °C	± 0.3 °C

<b>Calibration Status</b>	Pass	✓	Fail	
---------------------------	------	---	------	--

Calibrated By

Prabin KP (Service Engineer)

Approved By

Binoj Thomas (Quality Manager)



CALIBRATION CERTIFICATE

Certificate No.	MES/20-21/GHPI/VDRL/D01	Date of Issue	: 19/12/2020
		Calibration Done On	: 19/12/2020
		Calibration Due On	: 18/12/2021
Customer Name	GENERAL HOSPITAL, PALAI.		

DETAILS OF DEVICE UNDER CALIBRATION

Equipment Name	Make / Model	Serial No.	Asset ID	Location
VDRL Rotator	Kemi	2549	68058065	ICTC Lab

DETAILS OF MASTER EQUIPMENT USED

SI No.	Master Equipment	Make / Model	Serial No.	Reference ID	Cal. Due
1	Digital Tachometer	Equinox / EQ-801B	S916577	ACS/20-21/I02671-01	24/09/2021
2	Digital Thermo Hygrometer	Equinox / EQ-308CTH	20191602	ACS/MC/20-21/2593-01	18/06/2021

The instruments used for calibration are under valid calibration and are traceable to National Standards.

Environmental Conditions	Temperature	27°C	Relative Humidity	55 %
--------------------------	-------------	------	-------------------	------

PERFORMANCE DATA

Result	Obtained RPM
	89 rpm

Calibration Status	Pass	✓	Fail
--------------------	------	---	------

Calibrated By

Vivek Mahendran (Service Engineer)

Approved By

Binoj Thomas (Quality Manager)