

Abhcon Crown,X1/411/21,Ambadi Lane Kokkalai,Thrissur-21. Ph: 0487 2420367 Email: medengserv@gmail.com Visit us @www.mescalibration.com





## **CALIBRATION CERTIFICATE**

Certificate No. MES/20-21/GDHNR/REF/D10 Date of Issue : 31/12/2020 Calibration Done On : 29/12/2020 Calibration Due On : 28/12/2021

Customer Name GOVT. DISTRICT HOSPITAL, NILAMBUR, MALAPPURAM.

	DETAILS OF I	DEVICE UNDER C	CALIBRATION	
<b>Equipment Name</b>	Make / Model	Serial No.	Asset ID	Location
Refrigerator	Electrolux / Oxysmart	-	70100191	ICTC

	DETAILS OF MASTER EQUIPMENT USED				
SI No.	Master Equipment	Make / Model	Serial No.	Reference ID	Cal. Due
1	Digital Thermometer	Metravi / DTM 900	10055593	ACS/20-21/I02669-01	23/09/2021
2	Digital Thermo Hygrometer	Equinox / EQ-308CTH	20191602	ACS/MC/20-21/2593- 01	18/06/2021
	The instruments used for	calibration are under	valid calibration an	nd are traceable to National Sta	ındards

Environmental Conditions	Temperature	27.5 °C	Relative Humidity	52.0/
		27.5 0	rectative findingity	52 %

	PERFORMANCE DATA	
Display	Measured	Tolerance
1.2 ℃	1.3 ℃	± 0.3 °C
2.3 ℃	2.2 ℃	± 0.3 °C
4.1 ℃	4.1 °C	± 0.3 °C
7.2 °C	7.2 ℃	± 0.3 °C

Calibration Status Pass ✓ Fail

Calibrated By

Prabin K P (Service Engineer)

Approved By

Binoj Thomas (Quality Manager)

NB: Results reported are valid at the time of and under the stated conditions of measurements. This report shall not be reproduced without written approval by Medical Engineering & Services.

Page 1 of 1