

# TAX INVOICE

[See Rule 46 of the Central Goods and Services Tax Rules, 2017]

## TULIP DIAGNOSTICS (P) LTD

Regd Off "Gitanjali"-Tulip Block, Dr Antonio De Rego Bagh, Alto Santacruz, Bambolim Complex P.O. Goa 403 202 INDIA.

IRN: 67a04c24963ef45511d729565c37712e2057542d66280631c5ad97db1bb79656  
 INV NO: TAI1/0256/2021  
 29-Jan-2021



**Supplier Details**  
 Name: TULIP DIAGNOSTICS (P) LTD  
 Division Name:  
 Regd Office: "Gitanjali"-Tulip Block, Dr Antonio De Rego Bagh, Alto Santacruz, Bambolim Complex P.O. Goa 403 202 INDIA  
 GSTIN Unique ID: 30AAACT1411B1ZH  
 PAN NO: AAAC1411B  
 State: Goa  
 Works Address:  
 Warehouse Address:  
 Ref Date:  
 DL Nos: N/A  
 Wholesale DL Nos: NA  
 Transport:


**Customer Details / Bill To**  
 Code: C21B0009  
 Customer Name: BANSAL HOSPITAL  
 Customer Billing: C-SECTOR, SHAHPURA BHOPAL (M.P)  
 Address: Madhya Pradesh  
 Billing District/ State:  
 PAN NO:  
 Billing GSTIN: 23AABCA2560P1ZP  
 Billing Mob No: Madhya Pradesh  
 Shipping Mob No:  
 Billing State: Madhya Pradesh  
 Service To: BANSAL HOSPITAL  
 Consignee Name: C-SECTOR, SHAHPURA, BHOPAL (M.P)  
 Shipping Address: Madhya Pradesh  
 Shipping District/ State & Code: 23AABCA2560P1ZP

Sr.No	Product Description	UOM	Qty	Rate	Taxable Value	SGST Rate %	SGST Amt ₹	CGST Rate %	CGST Amt ₹	IGST Rate %	IGST Amt ₹	Total Amount
1	ANNUAL MAINTENANCE CONTRACT SAC 998719 For Lisawash - 4000Sr No: 591602027-E3A AMC Period From 20-Jan-21 TO 19-Jan-22	NOS	1	11000.0000	11000.00	0.00	0.00	18%	1980.00	0	0	12980.00
2	ANNUAL MAINTENANCE CONTRACT SAC 998719 For Lisaquant - TSSr.No: 451527026E AMC Period From 20-Jan-21 TO 19-Jan-22	NOS	1	11000.0000	11000.00	0.00	0.00	18%	1980.00	0	0	12980.00

Remarks:  
 Note:  
 Declaration: We declare that the supplier price shown above is sole consideration and certified that particulars given above are true and correct and the amount indicated represents the price actually charged and that there is no flow of additional consideration directly or indirectly from the buyer.  
 Amount in Words: Rupees Twenty Five Thousand Nine Hundred and Sixty Only

TAXABLE AMOUNT ₹	22000.00
SGST ₹	0.00
CGST ₹	0.00
IGST ₹	3960.00
NET AMOUNT ₹	25960.00

For, TULIP DIAGNOSTICS (P) LTD



Installation cum Warranty Certificate

Name & Address of Customer:

BANSAL HOSPITAL  
C - Sector, Shahpura  
Bhopal (M.P.)

Instrument Model: LISAWASH - 4000

Instrument Sr. No.: 691602027-E3A

Installation Date: 19/05/2014

Invoice No. TR/1/019/15

Invoice Date: 24/04/2014

Contact Person: Mr. Vikash Gupta

Phone No: 9893845512

AMC Due Date: 18/05/2016

Power supply details

Instrument connected to Online UPS Yes/No      Offline UPS Yes/No

Supply input to Machine from UPS: LN:      NE:      LE:

Supply input to UPS from Mains: LN:      NE:      LE:

Accessories Provided: main system, 8-pin manifold, Bottles, (a) waste bottle, (b) wash bottle, (c) water bottle, power cable, user manual, fuses, dust cover, cleaning solution, operation procedure card

Persons Trained:

Mr. Vikash Gupta

Demonstrated: yes.

Remarks: If any

Note: The above machine is satisfactorily installed at the site and staff adequately trained  
Received all accessories as per packing list



Name of Department Head:

Signature & Stamp

Date:



*Vikash Gupta*  
Tulip Diagnostics P Ltd.

Company's Sales & Service Engineer:

Signature

Date:

*D. J. J.*  
15/05/14

Tel: 0832-2458616, Fax: 0832-2458644, E-mail: sales@tulipgroup.com, Website: www.tulipgroup.com

Lic.No.-28C/3/2014

Bansal Hospital, Bhopal

TULIP DIAGNOSTICS (P). LTD. (INSTRUMENT DIVISION)

BAMBOLIM, ST-INEZ & VERNA - GOA

Ref SOP No. SOP/ID/013  
CC No: CC18/ID/001

CALIBRATION CERTIFICATE

Model: Lisawash 4000

Calibration Date: 25/01/2021

Sr. No.: 591602027 E3A

Calibration Due Date: 24/01/2022

Check Base plate & Top Cover Visually

Tick yes if OK, or else tick no,

- 1) Prime: - Level in the rinsing strip  
YES  NO
- 2) Rinse: - Level in the rinsing strip  
YES  NO
- 3) Plate wash: - Residual Volume (<3 µl)
  - Plate no. 1      400µl  
YES  NO
  - Plate no. 2      350µl  
YES  NO
  - Plate no. 3      300µl  
YES  NO
- 4) Strip wash: - Residual Volume (<3 µl)
  - Plate no. 1      400µl  
YES  NO
  - Plate no. 2      350µl  
YES  NO
  - Plate no. 3      300µl  
YES  NO
- 5) Dispensing: - Dispensing is without splashing or not
  - Without Rinsing  
YES  NO
  - With Rinsing  
YES  NO
- Dispensing Volume:
  - Plate no. 1      400µl  
YES  NO
  - Plate no. 2      350µl  
YES  NO
  - Plate no. 3      300µl  
YES  NO
- 6) Waste bottle: - Check for Waste Bottle sensor  
Message on Display & Beep when Bottle is Full  
YES  NO
- 7) Wash1 bottle: - Check for Wash1 Bottle sensor  
Message on Display & Beep when Bottle is empty  
YES  NO

FM/ID/029-00

Page 1 of 2

Corporate Office: Gitanjali, Tulip Block, Dr. Antonio De Rego Bagh, Alto Santacruz, Bambolim Complex P.O., Goa - 403 202, INDIA  
Tel.: (0832) 2458546-51, Fax: (0832) 2458544, E-mail: sales@tulipgroup.com, Website: www.tulipgroup.com

TULIP DIAGNOSTICS (P). LTD. (INSTRUMENT DIVISION)  
 BAMBOLIM, ST-INEZ & VERNA - GOA

Ref. SOP No: SOP/ID/013  
 CC No: CC18/ID/001

- 8) Wash2 bottle: - Check for Wash2 Bottle sensor  
 Message on Display & Beep when Bottle is empty YES  NO
- 9) Wash3 bottle: - Check for Wash3 Bottle sensor  
 Message on Display & Beep when Bottle is empty YES  NO
- 10) Water bottle: - Check for Water Bottle sensor  
 Message on Display & Beep when Bottle is empty YES  NO
- 11) Sensor cable: - Check for Sensor cable  
 Beep when sensor cable is not connected YES  NO
- 12) Incubator: - Check for temperature  
 Ambient, 25 °, 30 °, 37° C ± 1° C YES  NO

Measured Temperature	25°C, 30°C, 37°C
Displayed Temperature	25°C, 30°C, 37°C


13) Tools used

Description	Sr. No/ Model	Traceability
Digital Multimeter	MASTECH/MS8264	QATECH/GOA/01/20/IN121000002

- 14) Keyboard: -  
 Check all keys on keyboard by pressing  
 Them individually, beep should be heard when pressed. YES  NO
- 15) Display  
 Check all the characters are visible properly. YES  NO
- 16) Horizontal Movement  
 There should not be any sound or vibration YES  NO
- 17) Vertical Movement  
 There should not be any sound or vibration. YES  NO
- 18) Centering check  
 Check by reversing the Plate YES  NO

OTHER INSTRUCTIONS (IF ANY, PLEASE SPECIFY)

CALIBRATED BY: *ARM*



APPROVED BY: *[Signature]*  
*Boyd Dsc*

FM/ID/029-00

Page 2 of 2

Installation cum Warranty Certificate

Name & Address of Customer <b>BANSAL HOSPITAL</b> C Sector, Shahpura, Bhopal (M.P.)	Instrument Model <b>LISAQUANT - TS</b>
Contact Person <b>Mr. Vikash Gupta</b>	Instrument Sr. No <b>451527026E</b>
Phone No <b>9593845512</b>	Installation Date <b>19/05/2014</b>
Power supply details	Invoice No <b>TR/189/14</b>
	Invoice Date <b>25/03/2014</b>
	AMC Due Date <b>18/05/2016</b>

Instrument connected to Online UPS Yes/No      Offline UPS Yes/No

Supply input to Machine from UPS LN      NE:      LE:

Supply input to UPS from Mains LN:      NE      LE:

Accessories Provided **operator manual, mouse, jugs, dust cover, power cord, Touch pen & pen Bracket**

Persons Trained **Mr. Vikash Gupta**

Demonstrated: **yes.**

Remarks: If any

Note: The above machine is satisfactorily installed at the site and staff adequately trained  
Received all accessories as per packing list



Name of Department Head:  
Signature & Stamp  
Date:

**Vikas Gupta**

Company's Sales & Service Engineer:  
Signature  
Date:

**19/05/14**

Tulip Diagnostics P Ltd.

Gitanjali, Tulip Block, Dr. Antonio Do Rego Bagh, Alto Santacruz, Bambolim P.O. Goa. Pin: 403 202.

Tel: 0832-2458546/51 Fax: 0832-2458544, E-mail: sales@tulipgroup.com, Website: www.tulipgroup.com

**BLOOD BANK & COMPONENT CENTER**

Lic.No.-28C/3/2014

**Bansal Hospital, Bhopal**

**CALIBRATION CERTIFICATE**

Model: Lisaquant - TS

Sr. No.: 451527026E

Calibration Date: 25/01/2021

Calibration Due Date: 24/01/2022

**Check Base plate & Top Cover Visually**

**1) A/D VALUES**

WITHOUT MICROWELLS (AIR) (Range 6000-65000)

Tick YES if OK, or else tick NO.

FILTER	405	450	492	630
A	35137	36312	35810	36410
B	35182	35918	35318	36513
C	35168	35810	35751	36151
D	35124	36185	35789	36312
E	35218	36315	36011	36189
F	35310	36213	35721	36700
G	35217	36189	35719	37000
H	35157	35713	36319	36011

With in range YES  NO

**2) TOUCH PANEL**

Check the all Menu by clicking them individually with help of Touch pen, beep should be heard when clicked.

YES  NO

**3) DISPLAY**

Check all the Menu & characters on display are visible properly.

YES  NO

**4) EXTERNAL PRINTER CONNECTION**

Check printing.  
All characters should print properly.

YES  NO

**5) Horizontal Movement**

There should not be any sound or vibration.

YES  NO

**6) Centering checked**

By reversing the filmstrip check readings are Repeating or not.

YES  NO

## 7) MONOCHROMATIC DISTILLED WATER READINGS

YES  NO

Check water readings in Absorbance mode. It has to be Below 0.150 in new plate with 150µl water.

Reading of distilled water 450nm filter.

A1 well	B1 well	C1 well	D1 well	E1 well	F1 well	G1 well	H1 well
0.053	0.049	0.057	0.055	0.058	0.058	0.053	0.054

## 8) BIOCHROMATIC DISTILLED WATER READINGS

YES  NO

Check water readings in Absorbance mode. It has to be above 0.000 & below 0.050 in new plate with 150µl water.

Reading of distilled water 450nm and 630nm filter.

A1 well	B1 well	C1 well	D1 well	E1 well	F1 well	G1 well	H1 well
0.005	0.006	0.007	0.004	0.005	0.004	0.003	0.006

**PASSED**

(Tick yes if OK or else tick no, and give reason)

YES  No

CALIBRATED BY:

*Handwritten signature*



APPROVED BY:

*Handwritten signature*  
*Propd Osaura*

FM/ID/029-00

Page 2 of 2