



CUSTOMER CALL REPORT				
NO	2	90/3, Kamarajar Street, Old Suramangalam Salem - 636 005. India. Cell : 9361122309 Email : novamedisystems@hotmail.com		
Name Address <i>Life Care diagnostic Centre Dharmapuri</i>			<input checked="" type="checkbox"/>	SERVICE CALL DATE with Time
	Warranty	AMC	On Call	
	Nature of Vist			Month : <i>28/01/2021</i>
	Preventive Maintenance 1 2 3 4 5 6 7 8 9 10 11 12			
	Break Down			Voltage Details: <i>V-225-V</i>
	Installation			
Contact No.	Training			WORK HOURS <i>2 PM to 3 PM.</i>
	Application & Other			
INSTRUMENT DETAILS				
Model : <i>Microscope</i> S.No. <i>100329662</i>		Physical Condition		
Model : <i>Labimed</i> S.No. _____		Instrument Before Servicing		
Model : <i>Centrifuge</i> S.No. <i>2017095048</i>		GOOD <input checked="" type="checkbox"/>		
Model : <i>(Euro Diagnostic)</i> S.No. _____		DUSTY		
		SPARE PARTS USED		
NATURE OF COMPLAINT & OBSERVATIONS				
<i>Routine preventive maintenance</i>				
<i>Done -</i>				
DETAILS OF ACTION TAKEN				
<i>Lens Cleaning, Stage Adjustment,</i>			Spares & Service Charges	
<i>Lamp Change, general Service.</i>			Spares Cost in Rs. :	
			Service Charge in Rs.:	
ENGINEER REMARKS				
<i>Microscope, Centrifuge Working</i>				
<i>Good Condition.</i>				
NEXT SERVICE DUE ON : _____				
CALIBRATION DONE				
CALIBRATION DATE <i>28/01/2021</i>				
NEXT CALIBRATION DUE ON				
<i>29/08/2021</i>				
CUSTOMER REMARKS Instrument is Working Satisfactory If any				
Signature & Seal of Customer with Date				
 Signature of Engineer with Date & Time				