## Digital Thermometer Calibration Verification Record Sheet

Location: Room No.16, ICTC lab

Property No: ICTC Airoli

Procedure using Digital Thermometer: In house verification of Digital thermometer using standard

calibrated thermometer

Date: 16/04/2021

Certified thermometer ID: CRV/MICRO/VIRO/03/2017-18, 201705038856

Verification Done by: Ms Bandgar Rupali, Technical Officer, SRL, AFMC, Pune

Range of refrigerator: 2-8 Degree Celcius

Sr.No.	Time	Test Temp Degree Celcius	Certified Temp Degree Celcius	Temp Difference Degree Celcius -3.3	
1	12.00pm	9.4	6.1		
2	2 12.30 pm 8.9		5.8	-3.1	
3	1.00 pm	8.6	5.5	-3.1	
4	1.30 pm 8.3 5.4		5.4	-2.9	
Mean		8.8	5.7	-3.1	
SD		-	0.32	-	
%CV	Lister -	-	5.55	-	
% Accuracy=		-	-35.22727273	-	

Accept/ Reject: Rejected since correction factor is more than +/- 2.5 Degree Celcius

Final Interpretation: Digital thermometer needs to be replaced with new one

Action Taken: Reported to DAPCU, Thane and OIC, ICTC Airoli

Correction factor: -3.1

Remark: NA



3. Rupali Bandgar inical Officer MSACS :, Pune - 411 040

## Centrifuge Calibration Verification Record Sheet

Location: ICTC Lab, Airoli

Property No: ICTC RJH Airoli

Procedure using centrifuge: Inhouse verification of centrifuge using certified standard calibrated Tachometer

Date: 25/3/2021

Certified Tachometer ID: DT 2234-B

Verification Done by: Ms Bandgar Rupali, Technical Officer, SRL, AFMC, Pune

Sr.No.	Test	Certified Rotation (RPM)	Rotational Difference (RPM)	Test Rotation (RPM)	Certified Rotation (RPM)	Rotational Difference (RPM)	Test Rotation (RPM)	Certified Rotation (RPM)	Rotational Difference (RPM)
1	2500	2510	10	-	-	-	-	-	-
2	2500	2507	7	-		-	-	-	-
3	2500	2511	11		-	-			-
Mean	2500	2509.3	9.33	-	-	-		-	-
SD	-	2.08	-	-	-	-		-	-
%CV	-	0.08	-	1	-	-	-		
% Accura cy	-	0.372	-	-	-	0.6	-	ai-	-

Accept/ Reject: Accepted since average difference is within +/- 100 RPM

Final Interpretation: Centrifuge is in good working condition but it needs to be repaired or replaced with new one since it can be operated at a Single point

Action Taken: - Reported to DAPCU, Thane and OIC, Airoli

Remark: NA

Carl Carl

Ms. Rupali Bandgar Technical Officer SRL, MSACS AFMC, Pune - 411 040

## Timer Calibration Verification Record Sheet

ón: Room No.16, ICTC lab

sperty No: ICTC Airoli

ocedure using Timer: Inhouse verification of timer using certified standard calibrated Timer

ite: 24/04/2021

rtified timer ID: CRV/MICRO/VIRO/03/2017-18, DT-02

rification Done by: Ms Bandgar Rupali, Technical Officer, SRL, AFMC, Pune

Sr.No.	Timer Setting (Sec)	Certified Time (Sec)	Time Difference (Sec)	Timer Setting (Sec)	Certified Time (Sec)	Time Difference (Sec)	Timer Setting (Sec)	Certified Time (Sec) 899	Time Difference (Sec) -1
1	300	297	-3	600	599	-1	900	899	-1
2	300	298	-2	600	600	0	-	900	0
3	300	298	-2	600	601	1	900	899.3	-0.6
lean	300	297.7	-2.3	600	600	0	900	0.58	-
D	1	1.15	-	-	1.00	-	-	0.0642	-
CV		0.3878739			0.1666667	-	-		
Accuracy	-	-0.7666667		-	0	-	-	-0.077778	-

ccept/ Reject: Accepted since average difference is within +/- 60 Sec

nal Interpretation: Timer is in good working condition

ction Taken: -NA

emark: -NA

Ms. Rupali Bandgar Technical Officer SRL, MSACS AFMC, Pune - 411 040