

Maharashtra State AIDS Control Society

(Govt. of Maharashtra)

R.A.Kidwai Road, Acworth Leprosy Complex, Wadala (W), Mumbai 400031

MSACS/ICTC/ Document/ 2020-21 770-804 Date- 19/04/2021

LEGAL IDENTITY DOCUMENT

(To whomsoever it may concern)

The legal name of facility is Integrated Counseling and Testing Center (ICTC), Rajmata Jijau Hospital, Airoli, Navi Mumbai, Tal. Thane, Dist.-Thane.

The ICTC was established at Rajmata Jijau Hospital, Airoli, Navi Mumbai, Tal. Thane, Dist.Thane in the year: 2007 under the aegis of National AIDS Control Organization (NACO) and Maharashtra State AIDS Control Society (MSACS).

The ICTC, is legally responsible for providing HIV testing and counseling to client attending the facility.

(Chandrakant Dange, I.A.S.)
Project Director
Maharashtra State AIDS Control
Society, Mumbai,

EQAS External Quality Assessment Scheme for HIV Serology

REPORT (SRL to ICTCs)

Name of Proficiency Testing Provider: NARI, Pune

Round: II 2020-21

Name of Panel distributor Laboratory: AFMC, Pune

Name of the participating laboratory: Airoli MCH, Navi Mumbai

Date Panel Distributed: 29/01/2021

Sample Code	Standard Result	Results obtained by participating laboratory	% Matching	
A1	Non Reactive	Non Reactive	100%	
A2	Non Reactive	Non Reactive	100%	
A3	Non Reactive	Non Reactive	100%	
A4	Reactive	Reactive	100%	

Keyword: R: Reactive, NR: Non reactive

Remarks: Performance is Satisfactory / Unsatisfactory

विकृतीशास्त्रतज्ञ ज्ञा जिजाऊ रुग्णालय, ऐरोली न्या मुंबई महानगरपालिका.

CONFIDENTIAL

Signature of Laboratory Incharge: संतोष कराडे SANTOSH KARADE

ले कर्नल Lt Col

रीडर सूक्ष्म जीव विज्ञान विभाग Reader Dept ा Microbiology

स. से. चि. म. पुणे - 411 040

A. F. M. C, Pune - 411040

Digital Thermometer Calibration Verification Record Sheet

Location: Room No.16, ICTC lab

Property No: ICTC Airoli

Procedure using Digital Thermometer: In house verification of Digital thermometer using standard

Date: 16/04/2021

Certified thermometer ID: CRV/MICRO/VIRO/03/2017-18, 201705038856

Verification Done by: Ms Bandgar Rupali, Technical Officer, SRL,AFMC,Pune

Range of refrigerator: 2-8 Degree Celcius

Sr.No.	Time	Test Temp Degree Celcius	Certified Temp Degree Celcius	Temp Difference Degree Celcius -3.3	
1	12.00pm	9.4	6.1		
2	12.30 pm	8.9	8.9 5.8		
3 1.00 pm 4 1.30 pm		8.6	5.5	-3.1 -2.9	
		8.3	5.4		
Mean	-	8.8	5.7	-3.1	
SD -		-	0.32	-	
%CV -		-	5.55	-	
% Accuracy=	-	-	-35.22727273	-	

Accept/ Reject: Rejected since correction factor is more than +/- 2.5 Degree Celcius

Final Interpretation: Digital thermometer needs to be replaced with new one

Action Taken: Reported to DAPCU, Thane and OIC, ICTC Airoli

Correction factor: -3.1

Remark: NA

Rupali Bandgar inical Officer MSACS Pune - 411 040

Timer Calibration Verification Record Sheet

on: Room No.16, ICTC lab

sperty No: ICTC Airoli

Procedure using Timer: Inhouse verification of timer using certified standard calibrated Timer

Date: 24/04/2021

Certified timer ID: CRV/MICRO/VIRO/03/2017-18, DT-02

Verification Done by: Ms Bandgar Rupali, Technical Officer, SRL, AFMC, Pune

Sr.No.	Timer Setting (Sec)	Certified Time (Sec)	Time Difference	Timer Setting	Certified Time	Time Difference	Timer Setting	Certified Time	Time Difference
1	300	297	(Sec) -3	(Sec)	(Sec)	(Sec)	(Sec)	(Sec)	(Sec)
2	300	298	-2	600	599	-1	900	899	-1
3	300	298	-2	600	600	0	900	899	-1
Mean	300	297.7	-2.3	600	601	1	900	900	0
SD		1.15	-2.3	600	600	0	900	899.3	-0.6
%CV		0.3878739	-	-	1.00	-	-	0.58	-
% Accuracy			-	-	0.1666667	-	-	0.0642	-
Accept/ Reject	-	-0.7666667	-	-	0	-	-	-0.077778	-

Accept/ Reject: Accepted since average difference is within +/- 60 Sec

Final Interpretation: Timer is in good working condition

Action Taken: -NA

Remark: -NA

Ms. Rupali Bandgar Technical Officer SRL, MSACS AFMC, Pune - 411 040

Centrifuge Calibration Verification Record Sheet

ocation: ICTC Lab , Airoli

Property No: ICTC RJH Airoli

Procedure using centrifuge: Inhouse verification of centrifuge using certified standard calibrated Tachometer

Date: 25/3/2021

Certified Tachometer ID: DT 2234-B

Verification Done by: Ms Bandgar Rupali, Technical Officer, SRL, AFMC, Pune

	Test	Certified	Rotational	Test	Certified	Rotational	Test	Certified	Rotational
Sr.No.	Rotation	Rotation	Difference	Rotation	Rotation	Difference	Rotation	Rotation	Difference
	(RPM)	(RPM)	(RPM)	(RPM)	(RPM)	(RPM)	(RPM)	(RPM)	(RPM)
1	2500	2510	10	-	-	-	-	-	-
2	2500	2507	7	-	-	-	-	-	-
3	2500	2511	11	-	-	-	-	-	-
Mean	2500	2509.3	9.33	-	-	-	-	-	-
SD	-	2.08	-	-	-	-	-	-	-
%CV	-	0.08	-	-	-	-	-	-	-
% Accura	a -	0.372	-	-	-	-	-	-	-

Accept/ Reject: Accepted since average difference is within +/- 100 RPM

Final Interpretation: Centrifuge is in good working condition but it needs to be repaired or replaced with new one since it can be operated at a Single point

Action Taken: - Reported to DAPCU, Thane and OIC, Airoli

Remark: NA

Ball

Ms. Rupali Bandgar Technical Officer SRL, MSACS AFMC, Pune - 411 040