

STATE REFERENCE LABORATORY (SRL), B.J.G.M.C. PUNE

Centrifuge Calibration Verification Record Sheet

Location: ICTC Bhosari Hospital, Bhosari, Pune

Property No: ICTC/BHOSARI/INS/07

Procedure using centrifuge: Inhouse verification of centrifuge using certified standard calibrated tachometer

Date: ~~04/09/2018~~ 30/11/2021

Due Date: 03/09/2019 29/01/2022

Certified Tachometer ID: DR-69

Verification Done by: Mr. Vaijinath Munde, Technical Officer, SRL, BJMC, Pune


Sr.No.	Test Rotation (RPM)	Certified Rotation (RPM)	Rotational Difference (RPM)	Test Rotation (RPM)	Certified Rotation (RPM)	Rotational Difference (RPM)	Test Rotation (RPM)	Certified Rotation (RPM)	Rotational Difference (RPM)
1	1000	1011	11	2000	2014	14	3000	3019	19
2	1000	1006	6	2000	2015	15	3000	3018	18
3	1000	1012	12	2000	2016	16	3000	3011	11
4	1000	1013	13	2000	2017	17	3000	3041	41
5	1000	1019	19	2000	2019	19	3000	3017	17
Mean	1000	1012.2	12.2	2000	2016.2	16.2	3000	3012	12
SD	-	4.66	-	-	1.92	-	-	11.50	-
%CV	-	0.46	-	-	0.10	-	-	0.38	-
% Accuracy	-	1.22	-	-	0.81	-	-	0.4	-


Accept/ Reject: Accepted since rotational difference is less than 100rpm.

Final Interpretation: Centrifuge is in good working condition

Action Taken: -

Remark:


 Technical Officer
 S.R.L.T.
 Munde
 BJMC- Pune


 ICTC
 Incharge
 Incharge Medical Officer
 ICTC, Bhosari Hospital PCMC

MSACS

GOVT. OF INDIA - NACO-
NOT FOR SALE

MSACS / BH / ICTC / CENTRIFUGE - 2017 '05

R-4 LABORATORY CENTRIFUGE

REMI



Shot on vivo S1
AI Triple Camera