## Bio Matrix Technologies Pvt. Ltd.



G-114, 1st Floor, Madhura Nagar, Hyderabad - 500 038.

Ph: (040) 64525295, Mobile: +91 9553099998, E-mail: info@biomatrixtech.com, www.biomatrixtech.com



PERFORMANCE TEST REPORT FOR MICROSCOPE				
HOSPITAL NAME	ST. THERESA'S HOSPITAL, ERRAGADDA, HYDERABAD			
DEVICE	MICROSCOPE			
MAKE	OLYMPUS			
MODEL	CX21 IFS1			
SERIAL NO	18B0028			
EQUIPMENT ID	STH-BME-LAB-MIC-003			
DEPARTMENT	LAB			

PERFORMANCE STANDARD USED

S.NO	ASSET NO.	TEST EQUIPMENT	MAKE	MODEL NO	SERIAL NO	CAL DATE	CAL DUE DATE
1	BMT/12/07	ELECTRICAL SAFETY ANALYZER	FLUKE	ESA-612	2111026	24/08/20	23/08/21

ELECTRICAL SAFETY ANALYZER TEST RESULTS						
TEST	RESULTS	LIMITS				
Line(Mains)Voltage	236.7	0.0 to 300.0V ac rms				
Ground Wire Resistance	0.005Ω	0.000 to 2.000 Ω				
Equipment current	1.4A	0 to 20.0 A ac rms				
Insulation resistance	2 Μ Ω	+/-2% +0.2 M Ω				
Ground(Earth) Leakage	12 μA(AC+DC)	10 to 199 μA				
Chassis(Enclosure)Leakage	0.4 Ma	0.0 to 199.9 µA				
Lead to Ground and Lead to lead	0.4 μA(AC+DC)	0.0 to 1999 μA				
Lead isolation	0.6Ma	0.0 to 1999 µA				
Differential Leakage	0.2μΑ	0.0 to 1999 μA				
Direct Equipment Leakage	0.4μΑ	0.0 to 1999 μA				
Direct applied part Leakage	0.7μΑ	0.0 to 1999 μA				
Alternative applied part patient leakage	0.01Ω	0.0 to 1999 μA				
Point to point leakage, Voltage and Resistance	0.2μA,0.2v&OLΩ	+/-2% +0.2V				

ELECTRICAL SAFETY TEST PASSED AS PER IEC STANDARD 60601 1

Cal done date: 17-11-2020	Cal due date: 16-11-2021	
Calibrated by: N. PETER	Approved by: N. VENKAT	

O CASARRON (1)