Abhcon Crown,X1/411/21,Ambadi Lane Kokkalai,Thrissur-21. Ph: 0487 2420367 Email: medengserv@gmail.com Visit us @www.mescalibration.com



ELECTRICAL SAFETY TEST

Certificate No.

MES/20-21/PHCPY/BCA/D01

Date of Issue

19/03/2021

Calibration Done On Calibration Due On

11/03/2021 10/03/2022

Customer Name

PRIMARY HEALTH CENTRE, PANAVALLY, ALAPPUZHA.

DETAILS OF DEVICE UNDER CALIBRATION				
Make / Model	Serial No.	Asset ID	Location	
Mispa Viva	21153010118		Lab	
		Make / Model Serial No.	Make / Model Serial No. Asset ID	

DETA	ILS OF MASTER I	EQUIPMENT U	SED	
Master Equipment	Make / Model	Serial No.	Reference ID	Cal. Due
Electrical Safety Analyzer	Fluke / ESA612	2120517	ACCS200770	01/07/2021
Digital Thermo Hygrometer	Equinox / EQ-308-CTH	20191602	ACS/TH/20- 21/2593-01	18/06/2021
	Master Equipment Electrical Safety Analyzer	Master Equipment Make / Model Electrical Safety Analyzer Fluke / ESA612 Digital Thermo Hygrometer Equinox /	Master Equipment Make / Model Serial No. Electrical Safety Analyzer Fluke / ESA612 2120517 Digital Thermo Hygrometer Equinox / 20101603	Electrical Safety Analyzer Fluke / ESA612 2120517 ACCS200770 Digital Thermo Hygrometer Equinox / 20191602 ACS/TH/20-

Environmental Conditions	Temperature	27 °C	Relative Humidity	55 %

Calibration Status	Pass	1	Fail	
			I dii	

Calibrated By

Approved By

Amal Sasi (Service Engineer)

Binoj Thomas (Quality Manager)