

# Ace Medical Solutions (India) Pvt. Ltd.

An ISO 9001-2015 Certified Company

No : 3/751, 1st Cross Street, Surveyor Colony, K.Pudur, Madurai - 625 007.

Phone : 0452 - 2561691 Mobile : +91 94434 74610



GSTIN. 33AAHCA8053H1ZR • DL No. MDU/4205/20B,MDU/3971/21B • CIN : U33110TN2009PTC072140

## CALIBRATION CERTIFICATE



Customer Name & Address:	M/S. New Green Lab& Biopsy Centre, #1/786, Bharathi Nagar 7 <sup>th</sup> Street, Ramanathapuram – 623 503	Certificate No:	AMS/LAB/2889809
		Issuing Date:	25/09/2021
		Page No:	1 of 1

### Details of Device under Calibration (DUC):

DUC:	Centrifuge	Id. No:	NGC/LAB /CEN/001
Make:	REMI	Department:	Laboratory
Model:	R303	Calibrated On:	24/09/2021
Sl. No:	ZFIN 30815	Calibration	
Type:	---	Due Suggested:	23/09/2022
Range & Least Count:	0 – 4500 / LC - 1	DUC Condition on Receipt:	OK

### Traceability Details:

Sl.No.	Test Equipment	Make	Certificate Number	Valid Up to
1	Digital Tachometer	Mextech / DT-2234C	PC/01/21/ATL/0339-02	22/01/2022
2	Thermo Hygrometer	Beetech/088	PC/01/21/ATL/0194-01	22/01/2022

Room Temperature: 25°C±2

Room Humidity: 30-60%

(At the time of Calibration)

### Test Results:

SL.No.	DUC Reading	Standard Reading (RPM)	Correction (RPM)
1	Position1	1307	0
2	Position2	2457	0
3	Position3	3027	0
4	Position4	3502	0
5	Position5	4141	0

Allowable Tolerance: Set by Customer

Note:

1. Calibration Points were selected as per customer request.
2. Each reading were taken by Repeatability Test (i.e.) each reading in a row is a mean of 10 readings.
3. Results Reported are valid at the time of and under the stated conditions of measurements.

Calibrated By:

(Calibration Engineer)

*B. S. S.*



Approved by:

(Technical Manager)

*B. S. S.*