Ace Medical Solutions (India) Pvt. Ltd.

An ISO 9001-2015 Certified Company

No: 3/751, 1st Cross Street, Surveyor Colony, K.Pudur, Madurai - 625 007.





GSTIN. 33AAHCA8053H1ZR

DL No. MDU/4205/20B,MDU/3971/21B

CIN: U33110TN2009PTC072140

CALIBRATION CERTIFICATE



	M/S. Gowtham Diagnostic Centre,	Certificate No: AMS/LAB/288972	
Name & 744-B, Uthukuli Main Road, OPP. GH, Kunnathur, Tirupur Dt 638 103.	Issuing Date:	14/08/2021	
		Page No:	1 of 1

Details of Device under Calibration (DUC):

DUC:	Centrifuge	Id. No:	GDC/LAB/CEN/001
Make:	REMI	Department:	Laboratory
Model:	Manual	Calibrated On:	13/08/2021
Sl. No:	:	Calibration	13/06/2021
Type:	Manual .	Due Suggested:	12/08/2022
Range &	0-3500RPM/LC-1	DUC Condition	7
Least Count:		on Receipt:	OK

Traceability Details:

Test Equipment	Make	Certificate Number	Valid Up to
Digital Tachometer	Mextech / DT-2234C	PC/01/21/ATL/0339-02	22/01/2022
Thermo Hygrometer	Beetech/088		22/01/2022
	Digital Tachometer	Digital Tachometer Mextech / DT-2234C	Digital Tachometer Mextech / DT-2234C PC/01/21/ATL/0339-02

Room Temperature: 25°C±2

Room Humidity: 30-60%

(At the time of Calibration)

Test Results:

SL.No.	DUC Reading (Position)	Standard Reading (RPM)	Correction (RPM)
1	Position 1	1579	0
2	Position 2	2085	0
3 ·	Position 3	2447	0
4	Position 4	2703	0
5	· Position 5	3082	1 0

Allowable Tolerance: User Defined

Note:

- 1. Calibration Points were selected as per customer request.
- 2. Each reading were taken by Repeatability Test (i.e.) each reading in a row is a mean of 10 readings.
- 3. Results Reported are valid at the time of and under the stated conditions of measurements.

Calibrated By:

(Calibration Engineer)

B. 89:



Approved by:

(Technical Manager)

93455 56140, 93455 56148