

Instrument ID 277227	Instrument Model C111	Instrument Serial No. 13754	Visit Date 13/7/2021	<input checked="" type="checkbox"/> Engineering <input type="checkbox"/> Appearance <input type="checkbox"/> Other (pls specify)
--------------------------------	---------------------------------	---------------------------------------	--------------------------------	--

<input checked="" type="checkbox"/> Service Contract <input type="checkbox"/> Warranty <input type="checkbox"/> Advice <input type="checkbox"/> Placement / Rental <input type="checkbox"/> Other (pls specify)

Customer Name Reliance Industries Limited, Shandol	Contact / User Name Dr. Satvaprakash Singh
--	--

Call Received Date	Call Attended Dates	Treat Hours 19 hrs.	Work Hours 5 hrs	<input type="checkbox"/> In Station <input checked="" type="checkbox"/> Out-Station
--------------------	---------------------	-------------------------------	----------------------------	--

Problem Description
- Preventive Maintenance

- Action Summary:
- Removed dust from the Instrument.
 - Replaced all consumables from PM kit, mentioned below.
 - Lubricated all movable parts of the Instrument.
 - Cleaned Probe, sensor, rotor, and water/waste reservoirs.
 - Performed due maintenances and all PM checks.
 - Performed calibration, QC and samples, All results found ok.

UOM No.	Item	Qty	Batch No.	Total Value (Est)	Notes
28086842001	Seal Teflon 250 ul	1	-	-	
28136815001	Seal Cap Syringe	1	-	-	
2808731001	Filter fluid D13.8	1	-	-	

Service Engineer / Application Specialist Remarks: **Preventive maintenance done successfully.**
- Instrument working satisfactorily.

Customer Remarks:	Problem Resolved <input checked="" type="checkbox"/> Yes / <input type="checkbox"/> No
-------------------	---

Service Feedback: 1. Poor 2. Fair 3. Good 4. V.Good 5. Excellent

Service Engineer / Application Specialist Name Deepak Patidas	SP Address Seal	Customer's / User's Name Dr. Satya Prakash
Service Engineer / Application Specialist Signature @patidas		Customer's / User's Signature [Signature]

Defect Code	Function	Cause	Remedy	Cause	Code
-------------	----------	-------	--------	-------	------

