

Calibration Certificate

This is to Certify that Biochemistry Analyzer Meril AutoQuant-200Exelus Instrument Sr. No. AQ060444 Installed at Sachdeva Diagnostics, Delhi has been calibrated by our engineer on 01-Aug-2021 with appropriate and sophisticated tools. Below parameter has been calibrated:

TEST ITEMS AND RESULT

| Appearance | No Imbalance Probe Movement |
|----------------------------------|---------------------------------------|
| Leakage in Water tubing or CRU | No water leakage |
| Ambient temp (15-32) Degree | 24.0 degree C |
| Lamp Check | Ok |
| Sample Dispersing Volume | In range (0 to 30 ul) |
| Reagent cooling Temperature | 2.8 ° C (0 to 15 Degree) |
| Optical Path length | 0.65 |
| Waster & Water Sensor | Working Properly |
| Threshold value | ±34000 (≥25,000) |
| Valve & Motor | Working Properly |
| Reagent Dispensing Volume | In range (0 to 150 ul) |
| Power Supply and Earthing | 230 Volts and Grounding less then 5 V |
| CV-Kinetic/End point/two Point | CV- 1.77% /2.42% /2.80% |
| SD-Kinetic/End point/two Point | SD- 1.15/0.39/0.69 |
| Mean-Kinetic/End point/two Point | Mean- 97.55/14.34/24.79 |
| Hardware Check-Functional Test | OK5415152524141112 |
| Light Quality Check | OK |
| Cuvette Absorbance | OK |
| | OK >33000 |
| Cuvette Blank Value | 37.0 ° C |
| icubation temp. | 25.0 degree C |
| Room temp. | 23.0 degree d |

This Calibration Certificate is Valid Up to **01-Aug-2022.**Conclusion: All parameter are within range. The Machine is working properly.

(As per Meril terms.)

Engineer Name: Mr. Rahul Saini

Designation: Deputy Regional Service Manager

Engineer Sign:

T +91 260 3052100 F +91 260 3052125

www.merillife.com

Meril Diagnostics Pvt. Ltd. Survey No 135/2/B, Bilakhia House Muktanand Marg. Chala Vapi - 396191. Gujarat, India.

Diagnos