



c111 V4.1.0.1309 12
admin 17.06.2022 1:38

QC Details [CA2 - RANDOX - 06/22]:



c111 V4.1.0.1309 123
admin 17.06.2022 1:38

QC Details [CHO2I - RANDOX - 06/22]:




c111
admin

V4.1.0.1309

12323
17.06.2022 1:38 PM

QC Details [CHO2I - RANDOX - 06/22]:




c111
admin

V4.1.0.1309


12323
17.06.2022 1:39 PM

QC Details [CREJ2 - RANDOX - 06/22]:




c111

V4.1.0.1309




c111 V4.1.0.1309 12323
 admin 17.06.2022 1:39 PM

QC Details [CREJ2 - RANDOX - 06/22]:



c111 V4.1.0.1309 12323
 admin 17.06.2022 1:39 PM

QC Details [GLU2 - RANDOX - 06/22]:




c111
admin

V4.1.0.1309

17.06.2022 1:39 PM

QC Details [CREJ2 - RANDOX - 06/22]:




c111
admin

V4.1.0.1309

12323
17.06.2022 1:39 PM

QC Details [GLU2 - RANDOX - 06/22]:




c111
admin

V4.1.0.1309

12323
17.06.2022 1:39 PM

QC Details [HDLC4 - RANDOX - 06/22]:




c111
admin

V4.1.0.1309

12323
17.06.2022 1:39 PM

QC Details [HDLC4 - RANDOX - 06/22]:




c111
admin

V4.1.0.1309

17.06.2022 1:

QC Details [CA2 - RANDOX - 06/22]:




c111
admin

V4.1.0.1309

17.06.20

QC Details [CH02] - RANDOX - 06/2




c111
admin

V4.1.0.1309

17.06.202

QC Details [CREJ2 - RANDOX - 06/22



c111
admin

V4.1.0.1309


17.06.

QC Details [CLIP

c111
admin

V4.1.0.1309

QC Details [GLU2 - RANDOX




c111
admin

V4.1.0.1309

c111
admin

QC Details [HDLC4 - RANDOX - 06/22]:




c111
admin

V4.1.0.1309

17.06.2022

QC Details [TRIGL - RANDOX - 06/22]:



c111
admin

V4.1.0.1309

QC Details [UREL - RANDOX


0.5s
-1s
Set

V4.1.0.1309

17.06.20

c111
admin

QC Details [UREL - RANDOX - 06/22]



Roche Professional Services (ISO 9001:2015 certified)

Customer Support Center No: 1800-123-7599 /Toll No: +91-44-30413900



Case No.		Instrument Model	Cobas c111		
Order No.		Instrument Serial No.	12323		
Contract Type		Finance Status			
Lab/Inst./Hosp.Name	Medicentre Sonography and Clinical Lab				
Contact Name :	Shaitendra				
Contact Number :	7725937699				
Complete Address :	Near LIC Building ^{near} Hospital Road				
City :	Dungarpur				
Call Received Date/Time:	9/07/2022 10AM		Call Attended Date/Time:	9/07/2022 10AM	
Activity Type	Preventive Maintenance				
Problem Description					
Action Summary	Preventive Maintenance Done QC checked				
Spare Part Replaced					
Part No	Parts Description	Batch No	Batch Expiry Date	Qty.	Invoice Type
Time Report					
Effective Visit Date :			Complete Date:		
Date	Type(Travel/Labor Hour)	Start Time	End Time		
9/07/2022	Travel	8:00AM	10AM		
	Working Time	10AM	1PM,		
Customer's Signature Name :			Service Engineer/Application Specialist Name :	Manoj Vishwakarma	
MEDICENTRE SONOGRAPHY & CLINICAL LAB					
Date:	9/7/22		Date:	9/07/2022	
Disclaimer					
<p>1. This Service report has been signed by the authorized representative of your organization.</p> <p>2. Discrepancies if any must be intimated within a period of seven (7) days of the receipt of the email, in the absence of which the report will be final and conclusive.</p> <p>3. This report shall be governed by the laws of India and the courts at Mumbai shall have the exclusive jurisdiction to deal with the Disputes arising hereunder.</p>					