

CERTIFICATE OF CALIBRATION,
QUALITY CONTROL AND MAINTENANCE

To,
Sun Laboratory
Villupuram

This is to certify that the instrument **URA Serial No. 601826022IE**
Manufactured by **Medsource Ozone Biomedicals Pvt.Ltd** is under Calibration.
Quality control check up of the instrument has been the responsibility of
Medsource Ozone Biomedicals Pvt.Ltd

Date of Calibration

:25th June 2022

Calibration & quality control checks as recommended by the manufacturers in
operator manual are being performed regularly and satisfactorily.

This calibration certificate is valid up to 24th june 2023

For **Medsource Ozone Biomedicals Pvt. Ltd.**


Reshma UR
Service Coordinator
Mob: +91-96500 64495
GST No. 06AAAC05845J1ZA



Medsource Ozone Biomedicals Pvt.Ltd

Head office :Plot No.109,HSIIDC,Sector-31,Faridabad-121003,(Haryana),INDIA
Registered Office:238,Sant Nagar,East of Kailash,New Delhi-110065,INDIA
Telephone: +91-129-4286600 | E-mail:mail@ozonebio.com |Website: www.ozonebio.com
CIN:U85100DL2003PTC120213

CERTIFICATE OF CALIBRATION,
QUALITY CONTROL AND MAINTENANCE

To,
Sun Laboratory
Villupuram

This is to certify that the instrument **Eurocount tsSerial No. 850083**
Manufactured by **Medsource Ozone Biomedicals Pvt.Ltd** is under Calibration.
Quality control check up of the instrument has been the responsibility of
Medsource Ozone Biomedicals Pvt.Ltd

Date of Calibration

:25th June 2022

Calibration & quality control checks as recommended by the manufacturers in
operator manual are being performed regularly and satisfactorily.

This calibration certificate is valid up to 24th june 2023

For **Medsource Ozone Biomedicals Pvt. Ltd.**


Reshma UR
Service Coordinator
Mob: +91-96500 64495
GST No. 06AAAC05845J1ZA



Medsource Ozone Biomedicals Pvt.Ltd

Head office :Plot No.109,HSIIDC,Sector-31,Faridabad-121003,(Haryana),INDIA
Registered Office:238,Sant Nagar,East of Kailash,New Delhi-110065,INDIA
Telephone: +91-129-4286600 | E-mail:mail@ozonebio.com |Website: www.ozonebio.com
CIN:U85100DL2003PTC120213

