# Ace Medical Solutions (India) Pvt. Ltd.

An ISO 9001-2015 Certified Company No: 3/751, 1st Cross Street, Surveyor Colony, K.Pudur, Madurai - 625 007.

Phone: 0452 - 2561691 Mobile: +91 94434 74610



GSTIN. 33AAHCA8053H1ZR

DL No. MDU/4205/20B,MDU/3971/21B

CIN: U33110TN2009PTC072140

## **CALIBRATION CERTIFICATE**



Customer	M/S. Ramnad Clinical Laboratory,	Certificate No:	AMS/LAB/2889819
Name &	#16C, AKS Complex, R.R. Sethupathy Nagar,	Issuing Date:	25/09/2021
Address:	Ramanathapuram – 623 501	Page No:	1 of 1

**Details of Device under Calibration (DUC):** 

DUC:	Centrifuge	Id. No:	RCL/LAB/CEN/001
Make:	REMI	Department:	Laboratory
Model:	R303	Calibrated On:	24/09/2021
Sl. No:	ZBJN 29886	Calibration	
Type:		Due Suggested:	23/09/2022
Range &	0 – 4500 / LC - 1	DUC Condition	v
Least Count:		on Receipt:	OK

**Traceability Details:** 

Sl.No.	Test Equipment	Make	Certificate Number	Valid Up to
1	Digital Tachometer	Mextech / DT-2234C	PC/01/21/ATL/0339-02	22/01/2022
2.	Thermo Hygrometer	Beetech/088	PC/01/21/ATL/0194-01	22/01/2022

Room Temperature: 25°C±2

Room Humidity: 30-60%

(At the time of Calibration)

### **Test Results:**

OT N	DUC D 1'	Ctandard Danding (DDM)	Correction (RPM)
SL.No.	DUC Reading	Standard Reading (RPM)	Correction (KPIVI)
1	Position1	1236	0
2	Position2	2080	0
3	Position3	0	0
4	Position4	0	0
5	Position5	0	0

Allowable Tolerance: Set by Customer

#### Note:

- 1. Calibration Points were selected as per customer request.
- 2. Each reading were taken by Repeatability Test (i.e.) each reading in a row is a mean of 10 readings.
- 3. Results Reported are valid at the time of and under the stated conditions of measurements.

#### Calibrated By:

(Calibration Engineer)

B. 897



Approved by: (Technical Manager)

6.89=