# Ace Medical Solutions (India) Pvt. Ltd.

An ISO 9001-2015 Certified Company

No: 3/751, 1st Cross Street, Surveyor Colony, K.Pudur, Madurai - 625 007.

Phone: 0452 - 2561691 Mobile: +91 94434 74610



GSTIN. 33AAHCA8053H1ZR

DL No. MDU/4205/20B,MDU/3971/21B

CIN: U33110TN2009PTC072140

## **CALIBRATION CERTIFICATE**



Customer	M/S. Ramnad Clinical Laboratory,	Certificate No:	AMS/LAB/2889828
Name &	#16C, AKS Complex, R.R. Sethupathy Nagar,	Issuing Date:	25/09/2021
	Ramanathapuram – 623 501	Page No:	1 of 1

**Details of Device under Calibration (DUC):** 

DUC:	Protein Analyser	Id. No:	RCL/LAB/PA/001
Make:	AGAPEE	Department:	Laboratory
Model:	MISPA i3	Calibrated On:	24/09/2021
Sl. No:	21192210454	Calibration	
Type:	, , , , , , , , , , , , , , , , , ,	Due Suggested:	23/09/2022
Range &	4 4 4 4	DUC Condition	
Least Count:		on Receipt:	OK

Traceability Details:

Sl.No.	Test Equipment	Make	Certificate Number	Valid Up to
1	Electrical Safety Analyser	RigelSafeTest60	PSG/CIRD/BMCC/5507/2021	18/01/2022
2	Thermo Hygrometer	Beetech/088	PC/01/21/ATL/0194-01	22/01/2022

Room Temperature: 25°C±2

Room Humidity: 30-60%

(At the time of Calibration)

### **ESA Test Results:**

SL.No	Parameter	ESA Reading	Unit	Normal Range	Condition
1	Current	0.175	mA	1000	Normal
2	Frequency	50.0	Hz	49 -50	Normal
3	Mains Voltage Line - Neutral	220.3	Volts	220 - 240	Normal
4	Mains Voltage Line - Earth	223.4	Volts	220 - 240	Normal
5	Mains Voltage Neutral - Earth	5.7	Volts	< 7	Normal

<sup>\*</sup>Electrical Safety: Please check the attached log sheet

1. Functional Tests - Passed

### Note:

- 1. Calibration Points were selected as per customer request.
- 2. Each reading were taken by Repeatability Test (i.e.) each reading in a row is a mean of 10 readings.
- 3. Results Reported are valid at the time of and under the stated conditions of measurements.

## Calibrated By:

(Calibration Engineer)

B. 89:



Approved by:

(Technical Manager)

B.89.

