
Ace Medical Solutions (India) Pvt. Ltd.

An ISO 9001-2015 Certified Company

No: 3/751, 1st Cross Street, Surveyor Colony, K.Pudur, Madurai - 625 007.





GSTIN. 33AAHCA8053H1ZR • DL No. MDU/4205/208,MDU/3971/218 • CIN: U33110TN2009PTC072140

CALIBRATION CERTIFICATE

Name &	THE CENTRAL LABORATORY,	Certificate No:	AMS/LAB/289/1519
	96-B, Kanthan Colony Entrance, Palayam Kottai road,3 rd Mile, Tuticorin-8.	Issuing Date:	10/06/2022
		Page No:	1 of 1

Details of Device under Calibration (DUC):

DUC:	Centrifuge	Id. No:	BET/LAB/CEN/001
Make:	REMI	Department:	Laboratory
Model:	C-852/4	Calibrated On:	08/06/2022
Sl. No:	HLLO-6080	Calibration Due	00/00/2022
Type:	Analog - Manual Control	Suggested:	07/06/2023
Range & Least Count:	0 - 3500 / LC - 1; Timer 10 to 60Mins. In	DUC Condition on Receipt:	OK

Traceability Details:

Sl.No.	Test Equipment	Make	Certificate Number	Valid Up to
1	Digital Tachometer	Mextech / DT-2234C	PC/01/22/ATL/0432-01	30/01/2023
2	Thermo Hygrometer	Beetech/088	PC/01/22/ATL/0265-01	30/01/2023
3	Stop Watch	Nivia / JS 307	PC/01/22/ATL/0134-01	30/01/2023

Room Temperature: 25°C±2

Room Humidity: 30-60%

(At the time of Calibration)

Test Results: Rotation Per Minute

SL.No.	DUC Reading (RPM)	Standard Reading (RPM)	Correction (RPM)
1	Position I	1480	0
2	Position 2	2020	0
3	Position 3	2480	0
4	Position 4	2920	0
5	Position 5	3230	0

Allowable Tolerance: Set by Customer

Note:

1. Calibration Points were selected as per customer request.

2. Each reading was taken by Repeatability Test (i.e.) each reading in a row is a mean of 10 readings.

3. Results Reported are valid at the time of and under the stated conditions of measurements.

Calibrated By:

(Calibration Engineer)



Approved by:

(Technical Manager)



93455 56140, 93455 56148