
# Ace Medical Solutions (India) Pvt. Ltd.

An ISO 9001-2015 Certified Company

No: 3/751, 1st Cross Street, Surveyor Colony, K.Pudur, Madurai - 625 007.





GSTIN. 33AAHCA8053H1ZR

DL No. MDU/4205/20B,MDU/3971/21B
CIN: U33110TN2009PTC072140

# CALIBRATION CERTIFICATE

Customer	M/S.BETHEL CLINICAL LABORATORY,	Certificate No:	AMS/LAB/289/1516	
The state of the s	Name & 96-B, Kanthan Colony Entrance, Address: Palayam Kottai road,3 <sup>rd</sup> Mile, Tuticorin-8	Issuing Date:	10/06/2022	
Address:		Page No:	1 of 1	

Details of Device under Calibration (DUC):

DUC:	Micropipette	Id. No:	BET/LAB/VMP/003
Make:	ASTRA	Department:	Laboratory
Model:	AMP103LX	Calibrated On:	08/06/2022
Sl. No:	DY73563	Calibration Due	
Type:	Variable	Suggested:	07/06/2023
Range & Least Count:	100 – 1000μ1	DUC Condition on Receipt:	OK

Traceability Details:

Sl.No.	Test Equipment	Make	Certificate Number	Valid Up to
1	Electronic Weighing Scale	EWC/SF400C	PC/01/22/ATL/0432-02	30/01/2023
2	Thermo Hygrometer	Beetech/088	PC/01/22/ATL/0265-01	30/01/2023

Room Temperature: 25°C±2

Room Humidity: 30-60%

(At the time of Calibration)

### Test Results Volume µl:

SL. No.	DUC Reading (µl)	Standard Reading (µl)		Correction
		Trial 1	Trial 2	(µl)
1	100.0	110.00	110.00	+10.00
2	200.0	210.00	210.00	+10.00
3	500.0	500.00	500.00	+00,00
4	800.0	800.00	800.00	+00.00
5	1000.0	990.00	990.00	-10.00

Allowable Tolerance: User Defined

#### Note:

- 1. Calibration Points were selected as per customer request.
- 2. Each reading was taken by Repeatability Test (i.e.) each reading in a row is a mean of 10 readings.
- 3. Results Reported are valid at the time of and under the stated conditions of measurements.

## Calibrated By:

(Calibration Engineer)





Approved by:

(Technical Manager)

