
Ace Medical Solutions (India) Pvt. Ltd.

An ISO 9001-2015 Certified Company

No: 3/751, 1st Cross Street, Surveyor Colony, K.Pudur, Madural - 625 007.





GSTIN. 33AAHCA8053H1ZR

DL No. MDU/4205/20B,MDU/3971/21B

CIN: U33110TN2009PTC072140

CALIBRATION CERTIFICATE

	Customer	M/S.JEBA CLINICAL LABORATORY,	Certificate No:	AMS/LAB/289/1488
	Name & Address:	48, Bolden Puram Street, Near GH,	Issuing Date:	10/06/2022
l		Tiruchendur road, Tuticorin-628003	Page No:	1 of 1

Details of Device under Calibration (DUC):

DUC:	Centrifuge		
Make:	REMI	Id. No:	JCL/LAB/CEN/001
		Department:	Laboratory
Model:	C-852	Calibrated On:	08/06/2022
Sl. No:		Calibration Due	00/00/2022
Type:	Analog – Manual Control	Suggested:	07/06/2023
Range &	0 – 3500 / LC – 1; Timer 10 to 60Mins. In		07/00/2023
Least Count:	10Mins. interval	DUC Condition on Receipt:	OV
The state of the s		on Receipt:	l OK

Traceability Details:

Sl.No.	T . T			
51.140.	Test Equipment	Make	Certificate Number	Valid IIn to
1 1	Digital Tachometer			Valid Up to
		Mextech / DT-2234C	PC/01/22/ATL/0432-01	30/01/2023
2	Thermo Hygrometer	Beetech/088		
3			PC/01/22/ATL/0265-01	30/01/2023
DT	Stop Watch	Nivia / JS 307	PC/01/22/ATL/0134-01	30/01/2023

Room Temperature: 25°C±2

Room Humidity: 30-60%

(At the time of Calibration)

Test Results: Rotation Per Minute

SL.No.	DUC Reading (RPM)	Standard Reading (RPM)	Correction (RPM)
1	Position 1	1010	Correction (RPM)
2	Position 2	1620	0
3	Position 3	2110	0
4	Position 4	2380	0
5	Position 5	2990	0

Allowable Tolerance: Set by Customer

Note:

- 1. Calibration Points were selected as per customer request.
- 2. Each reading was taken by Repeatability Test (i.e.) each reading in a row is a mean of 10 readings.
- 3. Results Reported are valid at the time of and under the stated conditions of measurements.

Calibrated By:

(Calibration Engineer)





Approved by:

(Technical Manager)



93455 56140, 93455 56148