

TRICARE SERVICE SOLUTION

Puthenangady road, Kottayam : 686001.

Email Id: tricare@mail.com Ph: 0481-2934059


Mob: 8075224059

Performance Qualification

TEST	DARK CURRENT	BACKGROUND	STATUS
FILTER 340nm	111	51612	OK
FILTER 405nm	97	57544	OK
FILTER 505nm	83	56430	OK
FILTER 546nm	89	56714	OK
FILTER 578nm	81	55901	OK
FILTER 620nm	82	58312	OK
FILTER 660nm	79	54714	OK
FILTER 700nm	76	57860	OK

QUALITY CONTROL

TEST	QC LEVEL RANGE 1	TEST RESULT	QC LEVEL RANGE 2	TEST RESULT
GLUCOSE	73.5-102	88	240-333	270
CHOLESTEROL	225-272	243	89-114	100
TGL	160-206	179	83-117	101
ALBUMIN	3.72-4.65	4.1	2.5-3.2	2.8
SGPT	22-35	26	85-111	98
URIC ACID	5.43-7.63	6.68	8.21-9.9	9.3
SGOT	3.8-46.8	42	172-220	192

CUSTOMER REPORT	INSTALLERS REPORT
	Verified all the performance qualifications. It is successful
CUSTOMER DETAILS	Hi Tech Laboratory & ECG KFPSA Shopping Complex, Near Union Bank, Kulathupalam, Kumily 685509
SIGNATURE OF CUSTOMER	
INSTALLERS DETAILS	Tricare Service Solution XV111 357/C Puthanaggady Road Kottayam 682001
SIGNATURE OF THE INSTALLER	GOBIN JOSEPH 

When you look for **QUALITY IN SERVICE**