

No. 4346

FIELD SERVICE REPORT

Report No.	Instrument Model	Instrument Serial No.	Call Attending Date	Note of installation / Replacement:
43	PE-21	Priman S/N-1740	20/04/2017	

Charge Type:

<input type="checkbox"/> Service Contract	<input type="checkbox"/> Rental	<input type="checkbox"/> Paid Service	Service Charge Rs. _____
---	---------------------------------	---------------------------------------	--------------------------

Customer Details:

Lab/ Inst/Hosp Name & Address: RMRI Palna	Contact Person : Dr. C.S. Lall	Installation <input type="checkbox"/> PM Visit <input checked="" type="checkbox"/> Breakdown <input type="checkbox"/> Application <input type="checkbox"/>
Customer's Email Address:	Phone No.: 870 94 7567	

Problem Description:
- No -

Action Summary:

1. perform priming
2. perform cleaning
3. Run QC gives ok result

Condition After Service:
Instrument working properly

Customer's Remarks:

Engineer's Remarks:

Engineer's Name & Signature	Customer's Name & Signature with Stamp
Chandra 20/04/17	[Signature]

1. White-Record Copy
2. Pink-Customer Copy
3. Yellow-Engineer's Copy

No. 4360

FIELD SERVICE REPORT

Report No.	Instrument Model	Instrument Serial No.	Call Attending Date	Note of installation / Replacement:
4070	PE-21	S.N-1740	15/11/21	on Regent Rental Base


Charge Type:			
<input type="checkbox"/> Service Contract	<input type="checkbox"/> Rental	<input type="checkbox"/> Paid Service	Service Charge Rs. _____

Customer Details:		
Lab/ Inst/Hosp Name & Address: CDL, RMRMR, Agartala Patna	Contact Person : Dr. C. S. Lal, HOD Phone No.: 9825267492	Installation <input checked="" type="checkbox"/> PM Visit <input type="checkbox"/> Breakdown <input type="checkbox"/> Application <input type="checkbox"/>
Customer's Email Address:		

Problem Description: No.

Action Summary:
 * Check and install the instrument correctly.
 * Check all tubing, Housing and Electrodes
 * Perform calibration OK. Run QC 1 and 2
 Instrument gives satisfactory results. Run
 Sample all results are OK. So, satisfy customer.

Condition After Service: _____

Customer's Remarks: ok 

Engineer's Remarks: _____

Engineer's Name & Signature	Customer's Name & Signature with Stamp
 15/11/2021	 15/11/21

1. White-Record Copy
2. Pink-Customer Copy
3. Yellow-Engineer's Copy