



## CALIBRATION CERTIFICATE

Certificate No.	MES/21-22/THQHKT/CEN/J01	Date of Issue	: 15/01/2022
		Calibration Done On	: 04/01/2022
		Calibration Due On	: 03/01/2023

Customer Name	<b>TALUK HEAD QUARTERS HOSPITAL, KODUNGALLUR, THRISSUR.</b>
---------------	---

### DETAILS OF DEVICE UNDER CALIBRATION

Equipment Name	Make / Model	Serial No.	Asset ID	Location
Centrifuge	Remi/R – 8C Plus	-	70083112	Laboratory

### DETAILS OF MASTER EQUIPMENT USED

Sl No.	Master Equipment	Make / Model	Serial No.	Reference ID	Cal. Due
1	Digital Tachometer	Equinox / EQ-801B	S916577	ACS/SEP/21/I-45-01	19/09/2022
2	Digital Thermo Hygrometer	Equinox & EQ – 308 CTH	20191602	ACS/JUN/21/I – 32 -01	17/06/2022

The instruments used for calibration are under valid calibration and are traceable to National Standards.

<b>Environmental Conditions</b>	Temperature	27°C	Relative Humidity	55 %
---------------------------------	-------------	------	-------------------	------

### PERFORMANCE DATA

Set Reading	Display Reading	Measured Reading	Tolerance
Minimum	1000 rpm	1001 rpm	± 5 rpm
Medium	3000 rpm	3001 rpm	± 5 rpm
Maximum	5000 rpm	5001 rpm	± 5 rpm

Calibration Status	Pass	✓	Fail
--------------------	------	---	------

Calibrated By

  
 Amal Sasi (Service Engineer)

Approved By

  
 Binoj Thomas (Quality Manager)