

Vaidyanatheshwara Instruments Hac MR/

CERTIFICATE OF CALIBRATION





No. 301/A, 9th Main Road, 3rd Cross, Rajiv Gandhi Nagar, J.B. Kaval, Nandhini Layout Post, Bangalore - 560 096. Ph: 080-23377266, Mob: 9986586789 / 9632221171 / 9964308118 | Email: info@viplgroup.com Web: www.viplgroup.com

NABL Accredited Calibration Lab as per ISO/IEC 17025: 2017 With vide Certificate No: CC-2473

SRF No : 1722 : 20/10/2022 Report Date

Certificate No : VI/22-23/1722-08

Date of Calibration : 14/10/2022 **Date of Calibration Due** : 13/10/2023

Format No : VI/FRM/BIO-007

Customer Details : M/s. Citi Lab Healthcare (India) Pvt. Ltd.,

No.58, MM Road, Pulikeshi Nagar,

Bangalore-560 005.

Details of Device Under Calibration / Test:

Description : Microscope ID No.

Make : Olympus Serial No. : 15H0849 Model

: Ch20i Status : Working

Details of Calibration Standards Used:

Make & Model	Sr.No.	Valid upto	Traceable to
Electrical Safety Rigel 288+	17L- 1417	10-Aug-23	UKAS.UK

Environmental Condition Temperature: 25.1 °C Relative Humidity: 52 % RH

Calibration/Test Results

Instrument Location

: Lab

Electrical Safety Test:

SI.No	Parameters	Observed	Remarks
1	Voltage N-E	<3 Volt	PASS
2	Chassis leakage < 100 μA NC,< 500 μA SFC	4 μΑ	PASS
3	Earth Leakage < 100 μA B and BF CF	75 µA	PASS
4	Insulation test (optional) 500 V < 2 MΩ	>100MΩ	PASS

CALIBRATION STATUS: PASSED J

Note:

- 1. Electrical Safety Test Passed as per IEC Standard 60601.1
- 2. The above mentioned instrument has been calibrated using Manufacturing standards recommended protocols, using equipments having traceability to National/International Standards.

Calibrated By

(Calibration Engineer)

Checked By

Guruprasad

(Lab In-Charge)

