
Ace Medical Solutions (India) Pvt. Ltd.

An ISO 9001-2015 Certified Company

No: 3/751, 1st Cross Street, Surveyor Colony, K.Pudur, Madurai - 625 007.





GSTIN. 33AAHCA8053H1ZR

DL No. MDU/4205/20B, MDU/3971/21B

CIN: U33110TN2009PTC072140

CALIBRATION CERTIFICATE

Customer	M/S. Bharath Diagnostic Centre,	Certificate No:	AMS/LAB/289/1946
Name &	#71/12, Trichy main road,	Issuing Date:	03/09/2022
Address:	Namakkal - 637001	Page No:	1 of 1

Details of Device under Calibration (DUC):

DUC:	Centrifuge	Id. No:	BDC/LAB/CEN/002
Make:	REMI	Department:	Laboratory
Model:	R-8C	Calibrated On:	01/09/2022
Sl. No:	ANLC-12	Calibration Due	
Type:	Analog – Manual Control	Suggested:	31/08/2023
Range & Least Count:	0-3500 / LC-1; Timer 10 to 60Mins. In	DUC Condition on Receipt:	OK

Traceability Details:

Sl.No.	Test Equipment	Make	Certificate Number	Valid Up to
1	Digital Tachometer	Mextech / DT-2234C	PC/01/22/ATL/0432-01	30/01/2023
2	Thermo Hygrometer	Beetech/088	PC/01/22/ATL/0265-01	30/01/2023
3	Stop Watch	Nivia / JS 307	PC/01/22/ATL/0134-01	30/01/2023

Room Temperature: 25°C±2

Room Humidity: 30-60%

(At the time of Calibration)

Test Results: Rotation Per Minute

SL.No.	DUC Reading (RPM)	Standard Reading (RPM)	Correction (RPM)
1	Position 1	1198	0
2	Position 2	2247	0
3	Position 3	2397	0
4	Position 4	2754	0
5	Position 5	2975	0

Allowable Tolerance: Set by Customer

Note:

- 1. Calibration Points were selected as per customer request.
- 2. Each reading was taken by Repeatability Test (i.e.) each reading in a row is a mean of 10 readings.
- 3. Results Reported are valid at the time of and under the stated conditions of measurements.

Calibrated By:

(Calibration Engineer)

Approved by:

(Technical Manager)

93455 56140, 93455 56148

