

Ace Medical Solutions (India) Pvt. Ltd.

An ISO 9001-2015 Certified Company

No. 770/1, Jothi Complex 2nd Floor, Alagar Kovil Main Road, Surveyor Colony,
Madurai - 625 007, Tamilnadu, India Mobile : +91 94434 74610



GSTIN: 33ADSPA9153Q1ZA • DL No. TN-12-20B -00398, TN-12-21B-00398

CALIBRATION CERTIFICATE

Customer Name & Address:	M/S. Community Health Centre, Dharapuram Road, Vellakoil-638111.	Certificate No:	AMS/LAB/289/3058
		Issuing Date:	20/02/2023
		Page No:	1 of 1

Details of Device under Calibration (DUC):

DUC:	Centrifuge	Id. No:	PHCV/LAB/CEN/001
Make:	Microsil	Department:	Laboratory
Model:	T-10	Calibrated On:	18/02/2023
Sl. No:	70108-09	Calibration Due Suggested:	17/02/2024
Type:	Analog – Manual Control	DUC Condition on Receipt:	OK
Range & Least Count:	0 – 4500 / LC – 1; Timer 10 to 60Mins. In 10Mins. interval		

Traceability Details:

Sl.No.	Test Equipment	Make	Certificate Number	Valid Up to
1	Digital Tachometer	Mextech / DT-2234C	PC/01/23/ATL/0512-01	31/01/2024
2	Thermo Hygrometer	Beetech/088	PC/01/23/ATL/0215-01	31/01/2024
3	Stop Watch	Nivia / JS 307	PC/01/23/ATL/0210-02	31/01/2024

Room Temperature: 25°C±2 Room Humidity: 30-60% (At the time of Calibration)

Test Results:

SL.No.	DUC Reading (RPM)	Standard Reading (RPM)	Correction (RPM)
1	Position 1	1291	0
2	Position 2	2002	0
3	Position 3	3249	0
4	Position 4	3487	0
5	Position 5	4547	0

Allowable Tolerance: Set by Customer

SL.No.	DUC Reading (Minutes)	Standard Reading (Minutes)	Correction (Minutes)
1	10	10	0
2	20	20	0
3	25	25	0

Note:

1. Calibration Points were selected as per customer request.
2. Each reading was taken by Repeatability Test(i.e.) each reading in a row is a mean of 10 readings.
3. Results Reported are valid at the time of and under the stated conditions of measurements.

Calibrated By:

(Calibration Engineer)



Approved by:

(Technical Manager)