
# Ace Medical Solutions (India) Pvt. Ltd.

An ISO 9001-2015 Certified Company





GSTIN. 33ADSPA9153Q1ZA • DL No. TN-12-20B -00398, TN-12-21B-00398

## **CALIBRATION CERTIFICATE**

Customer	M/S. Primary Health Center,	Certificate No:	AMS/LAB/289/2498
Name &	#Authoor-628151	Issuing Date:	05/11/2022
Address:		Page No:	1 of 1

Details of Device under Calibration (DUC):

Demine of Device under Canoradon (Deco).						
DUC:	Microscope	Id. No:	APHC/LAB/MS/001			
Make:	Labomed	Department:	Laboratory			
Model:	Vision2000	Calibrated On:	03/11/2022			
Sl. No:		Calibration Due				
Type:	Binocular Opto Sys.	Suggested:	02/11/2023			
Range &		DUC Condition	,			
Least Count:	•	on Receipt:	OK			

Traceability Details:

Sl.No.	Test Equipment	Make	Certificate Number	Valid Up to
1	Electrical Safety Analyser	RigelSafeTest60	PSG/CIRD/BMCC/6908/2022	31/01/2023
. 2	Digital Lux Meter	HTC/ LX - 103	PC/01/22/ATL/0265-02	30/01/2023
3	Thermo Hygrometer	Beetech/088	PC/01/22/ATL/0265-01	30/01/2023

Room Temperature: 25°C±2

Room Humidity: 30-60%

(At the time of Calibration)

#### **ESA Test Results:**

SL.No	Parameter	ESA Reading	Unit	Normal Range	Condition
1	Current	238	mA	300	Normal
2	Frequency	50.0	Hz	49 -50	Normal
3	Mains Voltage Line - Neutral	231.5	Volts	220 - 240	Normal
4	Mains Voltage Line - Earth	238.4	Volts	220 - 240	Normal
5	Mains Voltage Neutral - Earth	8.8	Volts	< 7	Normal

<sup>\*</sup>Electrical Safety: Please check the attached log sheet

### Test Results: Light Intensity LUX:

SL.No.	Knob Position	DUC Reading (LUX)	Distance (Cm)	
1	Low	300	30	
2	Medium	8900	30	
3	High	19200	30\	

#### Note:

1. Calibration Points were selected as per customer request.

2. Each reading was taken by Repeatability Test (i.e.) each reading in a row is a mean of 10 readings.

3. Results Reported are valid at the time of and under the stated conditions of measurements.

Calibrated By:

aceagm@gmail.com

(Calibration Engineer)

amshealthcaremourcemail.com

Approved by:
(Technical Manager)

를 94434 74610, 93455 56148