



	CAI	IBRATION REPORT
Report No: HBMS/CAL/23-24		Calibration Date: 17.05.2023
		Calibration Valid: 16.05.2024
1.1.CUSTO	MER DETAILS:	
Name and Address of the organization		M/s, URBAN PRIMARY HEALTH CENTRE, CORPRATION HOSPITAL, K.K.PUDUR, COIMBATORE.
1.2. DESCI	RIPTION OF DEVICE UNDER TEST	(DUT):
EQUIPMENT NAME		CENTRIFUGE
i	Manufactured by	REMI
ii	Model	C-85416
iii	Serial No	ZCHN-24827

CALIBRATION WORKSHEET

LOCATION: LABORATORY

<u> Tabulation For – Centrifuge</u>

S.no	Unit under test IN Minutes	Observed speed tachometer in RPM	Deviation measured ± RPM	Combined uncertainty in RPM in % rdg
1	1000	1000	2	1.12
2	1200	1201	2	1.23
3	1500	1502	4	1.56
4	2000	1999	I	1.175

Acceptable deviation is ± 5 RPM it depends on Max Speed Range

Q

•

No. 23, 2nd Floor, jayasimmapuram, Pappanaikenpalayam, Coimbatore – 37.

99400 28355, 97512 06106 88833 15662

0

hbmedicalsystem@gmail.com hbmssales@gmail.com

A		
A care	-yh-	

no	Unit under test in minutes	Standard reading Digital Timer in minutes	Deviation measured in minutes
	05.0	05.1	0.1
1	05.0	10,2	0.2
2	10.0	10,2	0.1
3	15.0	15.1	0.3
	20.0	20.2	0.2

Acceptance deviation: ± 0.5 seconds

Testy equipment used

The calibration was performed by using Digital Multimeter & PT -100 sensor, Digital Timer (Stop Watch) and Digital Tachometer (non – contact) measured has been inspected in accordance with our inspection procedures to meets manufactures specification.

Remarks

This certificate may not be reproduced other than is full Except prior permission of laboratory.

Verified by:

9

No. 23, 2nd Floor, jayasimmapuram, Pappanaikenpalayam, Coimbatore – 37. 0

99400 28355, 97512 06106

88833 15662

 $>\!\!<$

hbmedicalsystem@gmail.com hbmssales@gmail.com