

## G MULTI SERVICES

78, Yahoob Street, Gobichettipalayam, Erode Dist, Tamil Nadu. Pin: 638 452. gmultiservicesgobiagmail.com. Cell: 96597 20654. Bio Medical Instruments Services

Er. A. Ibathul Raziq DECE., BE (ICE) Bio Medical Engineer

## Calibration Protocol & Report for Medical Equipment

Equipment : CENTRIFUGE

MAKE : REMI

MODEL : CENT100

PROTECT CLASS / TYPE : Risk Class I S. No.

: MI/CENT/001

Location

: GPHC, MINNAL

S.No		Measurement Parameters	Chahur	
2	Electrical Test  Physical Condition Test	(a)Safety Standards (range: 210-240 V) (b)Equipotential ground & Earthing (c)Risk of shock/fire Hazards, if any (d)Chassis & Insulation Resistance (e) Earth & Chassis Leakage Current (f) Battery conditions & charging status (a)Cabinet & Visible damages, if any (b) Front Panet/Top lid, buckets, motor aseembly & power cord	Status  230 volts 0 to 5 volts No Zero ohms 10mA NA NO OK	Remarks Stabilizer/UF With in Ranges Well Checked OK
	Performance Test	(c)Risk of mechanical damages, if any  (a) On /Off switch (b) Speed regulator switch & functional tests (c) Running test (d) Abnormalities (e) Display checkup (f) Keypad/indicators & connector (a) Vibration test (b) Speed regulation gradual hike/wobbling test (c) Running test with load (d) Display checkup	Normal OK Accurate OK No Well Well Done Ok	Ok Perfect Perfect
ormulated By Edition esearch Laboratory indorsed By: esearch team ead eviewed On: 06.09.23 ext Review: 05.09.24		Issued By:	User Department:	