




# MECOM SERVICES

Reg. Office:  
15/5870 - ST. MARY'S BUILDING, AM ROAD, SOUTHVAZHARILAM, ALIYA,  
COCHIN, KERALA  
IN. NUMBER: 2396 E. MAIL: info@calibration.com | Web: www.calibration.com



REPORT ON	
ELECTRICAL SAFETY TESTING/ PERFORMANCE ANALYSIS/ CALIBRATION	
Report No: MS/TR/22/M13	Calibration Date 10-08-2022
Page 1 Of 2	Calibration Due 10-08-2023
<b>1.1 CUSTOMER DETAILS</b>	
Name and address of the organisation	PRIMARY HEALTH CENTER MUDALUR, SANTHANKULAM TOOTHUKKUDI TAMILNADU-628702
Reference and Date	AS PER THE MAIL CONFIRMATION
Test performed by	MECOM team-1

1.2 DESCRIPTION OF DEVICE UNDER TEST (DUT)	
Nomenclature	CENTRIFUGE
A. Manufactured by	BOI
B. Model	BOI
C. Serial No.	BC1112
<b>1.3 CONDITION OF THE ITEM WHEN RECEIVED</b>	
No visible damage and in working order	
1.4 Applicable Specification	IEC Specification IEC 60601-1

1.5 Test Done	Performance Test and Electrical Safety Test
---------------	---

1.6 STATUS						
Manufactures Specification	Users Specification	Within Specification	Out of Specification	Calibration	Electrical Safety Test	Performance Analysis
✓		✓		✓	✓	✓

1.7 TRACEABILITY DETAILS OF INSTRUMENTS USED FOR TESTING					
Sl No	Name of the Instrument	Make	Model	Serial No	Cal Due
1	ELECTRICAL SAFETY ANALYZER	FLUKE	ESA 612	3005050	MAY 2023
2	DIGITAL TACHOMETER	LUTRON	DT-2230	Q655879	JUN 2023