

ASIAN TECHNOLOGY

(A HOUSE OF CALIBRATION)



CALIBRATION CERTIFICATE

Customer name	M/S: Shiv Diagnostic & Maternity	Service request No. & date	P/05/23/11/22&23/11/2022
'. And	Center	ULR no.	CC223922000005765 F
Address	Near Spectrum Mall Cort Road,	Cert. No.	AT/22000005765
	Kashpur- 244713 Distt. U.S.Nager	Date of Receipt of DUC	23/11/2022
	(Uttarakhand)	Date of calibration	23/11/2022
		Date of issue	24/11/2022
		Suggested due date	22/11/2023

	Instrun	nent Details	
Instrument name	Centrifuge	S. No.	ZBJN-27631
Make / Model No.	Remi / C-854/6	Location	
Range / Size	3500 rpm	I.D. No.	
Least Count	N/A	Visual Inspection	OK

Detail of reference standards & Major equipments used			
Equipment Name	Digital Hand Tachometer		
Make	LT Lutron		
Model / SR No.	/A.C92792		
Certificate No.	QCTS/000246/10		
Calibration Validity	21/10/2023		
Calibration by	Quality Calibration Testing Sol.		

Environmental	Temperature	20±2°C	Calibration Reference	IS: 12508
Condition	Relative Humidity	50±10 %	Calibration Procedure	CP-37

Calibration Results				
Serial No.	Position	Measured value in (rpm)	Uncertainty At 95% C.L. (coverage factor K=2)	
01.	Position: 1	1225		
. 02.	Position: 2	1554		
03.	Position: 3	1856	±0.2 %rdg.	
04.	Position: 4	2525		
05.	Position: 5	3458		

Remarks:

- (1) Standard equipment use for calibration are traceable to national/international standards. ٠
- (2) The reported expended uncertainty of measurement is stated as the standard uncertainty of measurement multiplied by coverage factork = 2 * such that the coverage probability corresponds to approximately 95%.(3)The above results are valid at the time of and under the stated conditions measurement.(4)This certificate is refers only to the particular item submitted for calibration. (5) Next calibration due date given as requested by the customer.

Calibrated By (Calibration Engg/TM) (MAHIPAL) Form No.-QF-47



Approved By (QM/TM) Page No. 1 of 1

---End of Report---