



# ALLWIN MEDICAL SYSTEMS

No. 2/4, 2nd Street, 1st Floor, Jayalakshmi Nagar,  
Kattupakkam, Chennai - 600 056, Tamilnadu, India,  
Cell : 9443663366  
Email : allwinmedicalsyste.ms@gmail.com

## CALIBRATION CERTIFICATE

Calibration Name & Address		Date : 09.06.2023
The Medical Officer Urban Primary Health Centre Krishnagiri	Certificate No	AWMS09B23

Details of Device Under Calibration (DUC)			
Description	: Centrifuge	Make	: Remi
Range	: 0-3000 RPM	Model	: BD153
Least Count	: ±10 RPM	Sr.No	: 76371
DUC Condition	:	Location	: Lab

Environmental Conditions & Calibration Procedure Details			
Environmental Details	Temperature: 25°C	Relative humidity	49%RH
Sample Calibration date	06.03.23	Calibration Done at	ON SITE

### CALIBRATION RESULTS

S.No	DEVICE UNDER CALIBRATION READINGS	STANDARD INSTRUMENTS READINGS	DEVIATION	EXPANDED UNCERTAINTY(±)
				25 RPM
				RPM
1	1200	1192	-08	Ok
2	1800	1794	-06	Ok
3	2400	2394	-06	Ok
4	3000	2997	-03	Ok

### Remarks

- 1.This Calibration Certificate Shall not be reproduced except in full, without written approval of the laboratory
- 2.The user Should be determine the suitability of the instrument for its intended use
- 3.The Recalibration interval should be determine on the User requirement.
- 4.The results Stated in this Certificate relate only to the item Calibrated
- 5.The indicated uncertainties are expanded uncertainty estimated for a confidence level of approximately 95% for coverage factor K=2.00
- 6.Equipment Used for Calibration were Calibrated & Traceable to National & International Standards

Calibrated By

Authorized Signatory

