

CPC DIAGNOSTICS PVT LTD REGISTERED OFFICE

No.9,5th floor,Gokul Tower, 9 & 10,CP Ramaswamy Road, Alwarpet,Chennai-600018 Tel:+91-44-24993989 Email:sales@cpcdiagnostics.in

CIN:U52599TN1991PTC021095

CALIBRATION CERTIFICATE

INSTRUMENT NAME : TURBOCHEM PRIME

SERIAL NO : 21193 SOFTWARE VERSION : 2.1.0.4

INSTALLAED AT : CARE PATHOLOGY LABORATORY, BHOPAL.

INSTALLAED ON : 27/07/2023 DATE OF CALIBRATION : 26/10/2023 NEXT CALIBRATION DUE : 25/10/2024

MECHANISM	REMARK				
SAMPLE/REAGENT TRAY					
	SAMPLE/REAGENT TRAY ROTATIONS REAGENT COOLING	OK OK			
_	CUVETTE UNIT	OK			
REACTION	CUVETTE UNIT				
	CUVETTE CONDITION	GOOD			
	CUVETTE ROTATION	GOOD			
	LAMP	GOOD			
	DRY BATH TEMPERATURE	OK			
	CUVETTE WASHING	GOOD			
	CUVETTE OVERFLOW	NOT HAPPENING			
PROBE MECHANISM					
	WASH POT ALIGNMENT	OK			
	REAGENT ASPIRATION POSITION (INNER)	OK			
	☐ REAGENT ASPIRATION POSITION (OUTER) OK				
	SAMPLE ASPIRATION POSITION(INNER)	OK			
	SAMPLE ASPIRATION POSITION(MIDDLE)	OK			
	SAMPLE ASPIRATION POSITION(OUTER)	OK			
	CUVETTE DISPENSE POSITION	OK			
	PROBE WASHING	OK			
	PROBE LIQUID LEVEL DETECTION	OK			



CPC DIAGNOSTICS PVT LTD REGISTERED OFFICE

No.9,5th floor,Gokul Tower, 9 & 10,CP Ramaswamy Road, Alwarpet,Chennai-600018 Tel:+91-44-24993989

Email: sales@cpcdiagnostics.in CIN: U52599TN1991PTC021095

MIXER MECHANISM

WASH POT ALIGNMENT	OK
MIXER WASHING	OK
MIXER ROTATION	OK
CUVETTE VS MIXER	OK

WATER AND DETERGENT TANK

WATER LEVEL SENSORS	OK
DETERGENT LEVEL SENSORS	OK
WATER HEATER	OK
LEAK IN WATER LINE	NOT HAPPENING

PHOTOELECTRIC STABILITY

Photoelectric stability gain should be in between 20000 to 60000

FILTER(NM)	GAIN
340	33372
405	37988
450	43058
510	40376
546	40454
578	39692
630	42485
670	44814

WE HERE BY CONFIRM **TURBOCHEM PRIME** HAS PASSED ALL THE ABOVE QUALITY CHECKS AND WORKING IN GOOD CONDITIONS.

KINDLY FIND ATTACHMENT OF PRECISION DATA FROM TURBOCHEM PRIME

For CPC DIAGNOSTICS PVT LTD.,

Authorised Signatory.