

Date: 26 Feb 2024

## Certificate of Calibration

Name & Address of Cus	tomer: <u>Sadar Ho</u> s	spital, Departn	nent of Patholo	ogy Sitam	arhi
City: <u>Sitamarhi</u>	State: <u>Bihar.</u>		_PIN:_843302	a	
Phone _		E-Mail _			
Name of Instrument: Se	lectra PRO M				
Type: Random Access F	ully Automatic Bio	ochemistry Ana	alyser		
Serial No: <u>21-4143</u>	-				
Calibration Date: 22 Apr	il 2024				
Next Calibration Due: 21	April 2025				
This is to certify that abore Filters, Aspiration, and Telitech Group Clinical Systems	Геmperature & La	has been vali mp according	dated of hardw to the proced	vare calibro dures prov	ation fo /ided b
This calibration is carried by Elitech Group, shown	out by using Standin the attachment.	dard Operatino	g Procedures (	S.O.P.) pr	ovided
These instruments conformal Calibration carried out on Signature & Stamp Name of Engineer/ Applications of Engineer Appli	site by:- Mr. Prasl cation Specialist: -	hant Ajit Mohan Du	R	n	

Encls.- SOP of Validation/Calibration along with data.



## Validation / Calibration - SOP

#### Selectra ProM

Name of the Customer & Address : Dept. of Pathology Sadar Hospital, Department of
Sadar Hospital Sitamarhi
Sr No: 21-4143
Status : Under warranty Validation & Preventive Maintenance
> Power Supply
Measure Input power Supply Voltage:229_V (230 V AC ± 10 V )
Check Earthling: 2.1 V ( 0 - 5 V)
Ambient temperature: 23 °C (10 - 35 °C)
Appearance : Clean (Clean/Dusty)
Bellow Pumps: Open the pump assays and clean it thoroughly.
Analyser Control Filter: Select the desired position through the Service menu. Filter wheel sets the desired Filter: Yes
Filter Status: Needs replacement (Yes/ NO) $_{\rho}$ 340nm $_{\rho}$ 405nm $_{\rho}$ 505nm $_{\rho}$ 546 nm $_{\rho}$ 578 nm $_{\rho}$ 620 nm $_{\rho}$ 660 nm $_{\rho}$ 700 nm
Note: Filter checked status was ok no need of replacement.
<b>Temperature</b> : Select the desired Options through the Service mode. Temperature OK: <b>Yes</b>
Pump: Select the desired volume through the Service mode

Verify by aspirating the same Quantity : OK

GSTIN; 09AAKFP4281G1ZY



Valve: Select the desired position through the service mode.

Valve is energized: Yes

Syringes: Check for syringe leakage by physical inspection of syringes.

No water leakage Found.

Cuvette Drier Block: Check the condition of cuvette drier block by removing the cover of cuvette rotor and lifting the wash arm through service menu. It should be reasonably clean. If dirty please change the drier block.

Note:- Condition of cuvette drier block is clean. No need to change.

Mixer Belts - Check the elasticity of mixer belts. Should be reasonably good or replace the belts.

Note:- Mixer belts are good no need to change.

Cuvette Rotor Blank: Perform rotor blank and check the OD values of cuvettes. All cuvette blank OD values should be within acceptable range. If required replace the cuvette rotor.

Note:- All cuvette blank OD values are in range no need to replace



## Hardware Calibration of Selectra Pro S/Pro M

## Lamp Calibration/Alignment

Lamp Adjustment :-

Flush the system with distilled water by doing Rotor Blank. 1.

Select Adjust Lamp in service menu. Check Value obtained on Display. (Adjust the lamp, if it is out of 1.800 to 4.000, to as low as possible)

## Do not touch lamp !! It may be Hot !!

Lamp alignment Data @ 340 nm wavelength					
Lamp Abs Obtained		Alignment	Remarks		
3.6396 Abs	1.800 to 4.200abs	Done	Lamp O.D.in acceptable range. No replacement required.		

## Checking the filters

Perform filter check in adjust lamp mode in service menu.

All the arrows must be in Green area. If not, then adjust lamp or replace filter if necessary.

#### Note:

When the absorbance value is too low to measure, i.e., the gain is too high, in this case, instead of the absorbance value, the value -99999 is shown.

Filter	Gain Range	Gain Achieved	Remarks	Corrective Action
(Wavelength)	0.1 - 3.5	2.3259	OK	Not required
340		1.6276	OK	Not required
405	0.1 - 2.6	0.6974	OK	Not required
505	0.1 - 2.6	0.6579	OK	Not required
546	0.1 - 2.6		OK	Not required
578	0.1 - 2.6	0.5205		Not required
620	0.1 - 1.2	0.4706	OK	Not required
660	0.1 - 0.7	0.5184	OK	
700	0.1 - 0.75	0.3644	OK	Not required
Over all Remarks	Filter gains with	in acceptable range	e. No replaceme	nt required.

If it is necessary to replace defective filters, please contact service department.



# ➤ Calibration/Verification of performance of Pipetting system & measuring unit

- Install dichromate solution on reagent rotor(s) & as sample on sample rotor (Use service disk which has Pre-defined protocol installed for dichromate run).
- Run 10x "Check-S" or 10x "Check-R" as QC samples.

Test	Target Value	Target CV [%]	Mean Result	CV [%]
Check-S	0.08(0.060-0.100)	≤2%	0.079	0.324
Check-R	1.75(1.500-2.000)	≤2%	1.752	0.810

#### Remarks:

Rotor Blank acceptable. Instrument ready for chemical installation & calibration.

- Change reagent disk from Service to Standard
- Install the various reagents on reagent rotor(s)
- Install ISE reagents on reagent rotor(s) (If applicable)
- o Run Reagent Blanks(s)
- Run Calibrations

### Volume calibration of pipettors:-

It is possible to check a predetermined amount of water to check the correct functioning of the pump. Before carrying out this check, the instrument must first carry out a flush routine to ensure that all system tubes are completely filled with water by doing fill system.

1. Go to Sample syringe full stroke. (For Pro M Model Only)

 Collect the dispensed water. Check the dispensed volume using calibrated pipette. Pro M only)



Pipettor	Calibration Data using distilled Water		
Full stroke volume to be dispensed (µI)	Dispensed volume checked and found complying as full stroke volume? (Yes/No)	Remarks	1
Sample Syringe:			
100	Yes	OK	
100	Yes	OK	
100	Yes	OK	
Reagent syringe:			
1000	Yes	OK	
1000	Yes	OK	
1000	Yes	OK	

#### Data for volumes other than full stroke:-

This can be verified using pre-determined amount of distilled water in sample/regent cups and running any dummy program. As soon as the reagent probe/sample probe takes up the sample/reagent, those cups/bottles are taken back and verified for remaining volume using calibrated pipette. Same can be repeated for variable volumes by changing the aspiration volumes in test programmes.

Pipp	etor Calibration Data	using distilled	Water	
Measured Volume taken in sample cup(µL)	Water to be aspirated by syringe(µL) (B)	Water that should be remaining in cup after aspiration(µL) (C=A-B)	Is the remaining volume inside the cup was found to be the same as in column C?  (Yes/No)	Remarks
Reagent syringe	8			
5000 μL	300 μL X 3 test =900 μL	4100 µL	Yes	OK
Sample syringe:	9			3
300 µL	30 μL X 3 test =90 μL	210 µL	Yes	OK

GSTIN: 09AAKFP4281G1ZY



## Temperature Calibration

Select Temperature in Service Menu. It should be 37 °C  $\pm$  2 °C Verify with temperature Indicator by surface probe in cuvette rotor. If any discrepancy add the offset of difference in actual & desired temperature.

	Tempe	rature Calibration I	Data	Tamp offset
Displayed Temp	-	Temp. Indicator	Temp Offset Required	Temp. offset
37° <b>C</b>	37 °C ± 2 °C	36.7° <b>C</b>	No	0 °C
Remarks	Temp. Calibrat	ion OK. No offset re-	quired.	



# ➤ Reagent Calibration of the Instrument

Customer is advised to verify the hardware calibration by reagent calibration. Use Elitech Calibrator Elical 2 for the calibration of all parameters.

User can do the same & attach the results in separate sheet with factors after verifying the same with Elitech Elitrol I & Elitrol II controls.All control values should fall within acceptable range.

Data sheets of the same should be attached along with this document.

Switch Off the instrument.

- Ensure all the Recommended Spares / Consumables have been replaced.(if not done during PM and required)
- Clean the instrument.

Close the cover.

Recommended Spares for replacement : NIL

We hereby certify that Validation have been carried out under the MOU. Hardware Calibration of Lamp, Filters, Temperature & Aspiration (Pump) has been done successfully.


Please perform the standardization / Calibration and verify by evaluating controls before processing patient samples.

Next Calibration is due on: 22 Feb. 2025.

Signature of Application Specialist

Place

Date.



Lamp

Return

23-Feb-2024 HOST 09:26:48 AM DUAL MODE Req./tray buffer:0/1 Standard Loadable Inactive -Lamp adjustment-▶ Adjust Lamp Cuvette Lamp 04:57 absorbance absorbance Reagent Arm Please wait for 5 minutes (see above clock) to let the lamp stabilize. Sample Arm Loosen the screw with the spring. Reagent Disk Adjust the other two screws such that the lamp absorbance and the cuvette Sample Disk / Barcode -3.8 -3.6 -3.4 -3.2 -3.0 -2.8 -2.6 -2.4 -2.2 -2.0 absorbance fall within the green range and are as low as possible. Measurement Disc/Filter Also, check for the first 5 filters, if the Wash Arm absorbance has a decreasing "profile". Pipettor Then do a filter check by inspecting if all values fall within the green range. If not, adjust the lamp again such that the Vacuum system absorbance values are a little bit higher. Water system When finished, tighten the screw with the spring. Optical electronics 2.5663 3.6396 **Flectronics** 

F10

23-Feb-2024 09:47:29 AM

Last blank date:

time:

F1

5

Print

=44


F2


Blank Rotor





































Main Menu



#10 Check S

#2 Check S

0.079 Abs

0.087 Abs

