



FACTORY & REGISTERED OFFICE :
424, NEW GIDC, KABILPORE, NAVSARI - 396 424. (INDIA)
PH. : +91-2637-265590, 265791 FAX : +91-2637-265105
E-mail : sales@beaconindia.com Website : www.beaconindia.com
CIN No. : U24232GJ1990PTC013764

Calibration Certificate

Calibration of the **B AUTO 200** (Fully auto Chemistry Analyzer) has been carried out as per the recommendations of the principle company.

Customer Name : **DIAGNOSCAN IMAGING & DIAGNOSTICS,LUCKNOW,UP**

Calibration Date : **16/03/2024.**

Next Calibration Due On: **15/09/2024.**

KP Nal

Checked By:



FACTORY & REGISTERED OFFICE :
 424, NEW GIDC, KABILPORE, NAVSARI - 396 424. (INDIA)
 PH. : +91-2637-265590, 265791 FAX : +91-2637-265105
 E-mail : sales@beaconindia.com Website : www.beaconindia.com
 CIN No. : U24232GJ1990PTC013764

Performance Qualification

MODEL: B AUTO 200	Sr. No. AES2K2KH01216A	Version: V.4.8.5.0	Date: 16-03-2024
-------------------	------------------------	--------------------	------------------

PQ is performed at

DIAGNOSCAN IMAGING & DIAGNOSTICS,LUCKNOW,UP

According to the assay results that are comprised in this document the B AUTO 200 systems can be approved for the routine operation.

System released for routine operation.

PERFORMANCE CALIBRATION			
LOT No: LP13-040			
TEST	TARGET	RANGE	RESULT
GLU	279	0.00-1.00	105.40
CRE	4.59	0.60-1.10	1.68
BIL-T	1.48	0.00-1.00	1.57
ALB	2.95	3.40-5.50	4.10
TP	4.57	6.00-8.00	5.68
TG	255	60.00-170.00	99.35
UREA	120	10.00-40.00	48.99



FACTORY & REGISTERED OFFICE :
424, NEW GIDC, KABILPORE, NAVSARI - 396 424. (INDIA)
PH. : +91-2637-265590, 265791 FAX : +91-2637-265105
E-mail : sales@beaconindia.com Website : www.beaconindia.com
CIN No. : U24232GJ1990PTC013764

UA	9.31	4.00-7.20	5.94
CHO	290	130.00-250.00	147.09

Note: Performance of the parameters are subject to traceability of Reagents, Manufacturer or Supplier.

KP Nair

Checked By:



FACTORY & REGISTERED OFFICE :
424, NEW GIDC, KABILPORE, NAVSARI - 396 424. (INDIA)
PH. : +91-2637-265590, 265791 FAX : +91-2637-265105
E-mail : sales@beaconindia.com Website : www.beaconindia.com
CIN No. : U24232GJ1990PTC013764

Operational Qualification

MODEL: B AUTO 200	Sr. No: AES2K2KH01216A	Version: V.4.8.5.0	Date: 16-03-2024
-------------------	------------------------	--------------------	------------------

Operational Qualification Protocol run at DIAGNOSCAN IMAGING &
DIAGNOSTICS,LUCKNOW,UP

#	Description	Status
1	Blank/Optics	OK
2	Assays(Parameter) Calibration	OK
3	Assay (Parameter) Control – RANDOX	OK
4	Assays(Parameter) Samples(Patient)	OK
5	Programming and operational training completed	OK
6	Instrument operating training completed	OK

I confirm that the above specified analyzer B AUTO 200 (Fully auto Chemistry Analyzer) is installed properly and its performance is within the specification.

Checked By:



FACTORY & REGISTERED OFFICE :
 424, NEW GIDC, KABILPORE, NAVSARI - 396 424. (INDIA)
 PH. : +91-2637-265590, 265791 FAX : +91-2637-265105
 E-mail : sales@beaconindia.com Website : www.beaconindia.com
 CIN No. : U24232GJ1990PTC013764

Installation Qualification

MODEL: B AUTO 200	Sr. No: AES2K2KH01216A	Version: V.4.8.5.0	Date: 16-03-2024
--------------------------	-------------------------------	---------------------------	-------------------------

Installation of the **B AUTO 200** (Fully auto Chemistry Analyzer) at **DIAGNOSCAN IMAGING & DIAGNOSTICS, D-3019, GROUND FLOOR HALL, MUNSHI PULIA, INDIRA NAGAR, LUCKNOW, UP**

The Installation Checklist is as given below:-

#	Position	Action	Status
1	Unpacking	Unpack the Complete System	OK
2	Inventory	Check Accessories With packing list	OK
3	Installation	Connection Of Pipeline Connection Of the Equipment Installation Of Software	OK
4	Service	Executing Air Purge Checking Syringe Sample and Reagent Probe Reaction Disk	OK
5	User	Start Work Procedure Check Reagent & DDW Cell blank Test Run QC Run Samples/Check Reproducibility Stop Work Procedure	OK

KPN

Checked By: